

(These four lines should be repeated at the commencement of the measurements relating to each work).

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of the Work:					
Repair of Road breaches (Damaged by flood) for motorability in PWD Sathi to Lakshnawta.					
Work Head: FDR					
MEASUREMENT = 585.83 m ³					
Item No-1/1					
Earthwork - Construction of embankment with approved material					
$1 \times 20.00 \times \frac{2.60 + 2.40}{2} \times \frac{0.40 + 0.2}{2}$					
= 15.00 m ³					
$1 \times 30.00 \times \frac{2.25 + 2.15}{2} \times 0.75$					
= 43.20 m ³					

Continuation

$$= 46.08 \text{ m}^3$$

104.28 m³

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
ABSTRACT					
Item No- 1/1					135.01%
Earthwork - Construction of embankment with approved material - 7/5					100.00%
From T.M. B. page no- 1					148.33
					Qty = 104.28 m ³
					@ Rs. 130.50 / m ³
					= Rs. 13608.54

Item no-2/2

Providing Material and Labour for laying dry graded Bricks Bats — 7/5

From T.M. B. page no-2

Qty = 472.91 m³@ Rs. 1810.36/m³

= Rs. 856137.35

Rs. 869745.89

Add S.F. = Rs. 48457.95

Add L.C. @ 1% = Rs. 8697.46

Add G.S.T. @ 12% = Rs. 104369.51

Continuation

Rs. 1031270.81

Jayshree K.
30.09.2020
J.E.

48 *[Signature]*
11/10/2020
26/12/2021
EE