

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD		
Name of Scheme: <u>Harkhali - Bhakhari Sahan</u>		
Hazards	Flood/Rain	
Division : <u>Baizi</u>	District: <u>Purnea</u>	Actual Length (in km): <u>3.744</u>
Damage Length (in km): <u>0.289 km</u>	Damages Location/Chainage: <u>2.300 km to 2.589 km</u>	
Name of Scheme/Programme:	<u>FDR (3054)</u>	
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	<u>S</u>
a)	Condition of Surfacing	<u>S</u>
Description of observation : <u>MSS Surfacing work is in good condition.</u>		
b)	Adequate Thickness of pavement layers constructed	<u>S</u>
Description of observation : <u>GSB Gr-II - 175 mm</u> <u>WBM Gr-II - 75 mm</u> <u>WBM Gr-III - 75 mm</u> <u>MSS - 20 mm</u>		
c)	Quality of Construction Material Used	<u>S</u>
Description of observation : <u>Good quality material used</u>		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>N.A.</u>
Description of observation : <u>N.A.</u>		
e)	Compaction of flanks/ slope & raincuts	
Description of observation : <u>Plank work in progress</u>		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	<u>S</u>
b)	Condition of Vent Clearance	<u>S</u>
c)	Condition of railings/Slab/approach for Bridges	<u>N.A.</u>
Description of observation of CD works : <u>Found in good condition</u>		
Remark if any: <u>Work is in good condition</u>		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	<u>S</u>
---------------------------------------	----------

Name of Officer: Ratnesh Paswan

Designation: E.E.

Ratnesh
23/06/21
A.E.

23-6-21
(Signature)
E.E.