

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Karnal Pur PWD Road To Urfaul
 Hazards: Flood/Rain Flood
 Division: Forbishgarj District: Araria Actual Length (in km): 7.20
 Damage Length (in km): 0.10 Damages Location/Chainage: 7th km

Name of Scheme/Programme: F.D.R BUSY
 Status of Project: Under Agreement/Out of Agreement

Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	S

Description of observation : Surface road condition

b)	Adequate Thickness of pavement layers constructed	S
----	---	---

Description of observation : EnSB Gr II 100mm
WBM Gr II 75mm
m-SS 20mm
total 195mm

c)	Quality of Construction Material Used	S
----	---------------------------------------	---

Description of observation : Quality of material good

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	NA
----	---	----

Description of observation :

e)	Compaction of flanks/ slope & raincuts	<u>NA</u>
----	--	-----------

Description of observation : Earth work in progress in Flank

2	Cross Drainage Structure	
---	--------------------------	--

a)	Condition of head walls in Hume pipe culverts	
----	---	--

b)	Condition of Vent Clearance	
----	-----------------------------	--

c)	Condition of railings/Slab/approach for Bridges	
----	---	--

Description of observation of CD works :

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer:

Bindu Rajan

Designation:

Executive Engineer,
R.W.D.,
Regional Laboratory
Darbhanga

23/06/21
A.E.

(Signature)

23/06/21