

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: NH 104 GAUSHALA TO KHAIRNA		
Hazards	Flood/Rain	
Division: R.W.D. (W) SITAMARHI	District: SITAMARHI	Actual Length (in km): 2.50 km
Damage Length (in km): 0.200 km	Damages Location/Chainage: 1.200 km to 1.400 km	
Name of Scheme/Programme:	FDR	
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks: (S/U)
1.	Pavement (BT/CC) B.T	
a)	Condition of Surfacing	S
Description of observation : MSS Surfacing work found in good condition.		
b)	Adequate Thickness of pavement layers constructed	S
Description of observation : GSB - 200 mm WBM - 75 mm MSS - 20 mm		
c)	Quality of Construction Material Used	
Description of observation : Good quality crust material		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	NA
Description of observation : NA		
e)	Compaction of flanks/ slope & raincuts	S
Description of observation : Condition of flank is good		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	S
b)	Condition of Vent Clearance	S
c)	Condition of railings/Slab/approach for Bridges	N/A
Description of observation of CD works : Found in good condition.		
Remark if any:		
Overall Rating		

Satisfactory (S) / Unsatisfactory (U)	S
---------------------------------------	---

Name of Officer: CHANDRA SHEKHAR AZAD

Designation: B.E.

22/06/21
A.E.

22/6/21
(Signature)