

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: ITI SHANTINAGAR TO NH 77 NAHAR CHAUK

Hazards Flood/Rain

Division : R.W.D (W) SITAMARHI District: SITAMARHI Actual Length (in km): 1.300 Km

Damage Length (in km): 0.300 Km Damages Location/Chainage: 0.200 Km To 0.500 Km

Name of Scheme/Programme: FDR

Status of Project: Under Agreement/Out of Agreement

Sr. No. Parameters to be Checked in Restoration work Remarks : (S/U)

1. Pavement (BT/CC) B.T

a) Condition of Surfacing S

Description of observation : MSS Surfacing work found in good condition.

b) Adequate Thickness of pavement layers constructed S

Description of observation :
G.S.B - 200 mm
W.B.M - 75 mm
M.S.S - 20 mm

c) Quality of Construction Material Used S

Description of observation : Good quality crust material used

d) Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.

Description of observation : N.A.

e) Compaction of flanks/ slope & raincuts

Description of observation : Condition of flank is good

2 Cross Drainage Structure

a) Condition of head walls in Hume pipe culverts NA

b) Condition of Vent Clearance NA

c) Condition of railings/Slab/approach for Bridges NA

Description of observation of CD works : NA

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer: CHANDRA SHEKHAR AZAD

Designation: E.E.

[Signature]
22/6/21

[Signature]
22/6/21
(Signature)