

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Sukhi Musharriya to Bhaugawa
 Hazards: Flood/Rain
 Division: Sitamari District: Sitamari Actual Length (in km): 3.250
 Damage Length (in km): 0.175 Damages Location/Chainage: PDR
 Name of Scheme/Programme: PDR
 Status of Project: Under Agreement/Out of Agreement

Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	S

Description of observation :

MSS Surfacing work found in good condition.

b)

Adequate Thickness of pavement layers constructed

S

Description of observation :

Adequate thickness found.

c)

Quality of Construction Material Used

S

Description of observation :

Good quality material found.

d)

Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.

Description of observation :

NA.

e)

Compaction of flanks/ slope & raincuts

S

Description of observation :

Found in good condition.

2

Cross Drainage Structure

a)

Condition of head walls in Hume pipe culverts

S

b)

Condition of Vent Clearance

S

c)

Condition of railings/Slab/approach for Bridges

NA

Description of observation of CD works :

Found in good condition.

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

'S'

Name of Officer: CHANDRA SHEKHAR AZAD

Designation: E.E.

Ch
23/06/21
(Signature)

23/06/21
A.E.