

INSPECTION REPORT FOR FLOOD/RAIN DAMAGE ROAD

Name of Scheme: <u>PARMANANDPUR TO PARARI</u>		
Hazards	Flood/Rain	
Division: <u>R.W.D.</u>	District: <u>SITABDI</u>	Actual Length (in km): <u>3.57 km</u>
Damage Length (in km): <u>0.170 km</u>	Damages Location/Chainage: <u>2.600 km to 2.770 km</u>	
Name of Scheme/Programme: <u>FDR</u>		
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks: (S/U)
1.	Pavement (BT/CC) <u>B.T</u>	<u>S</u>
a)	Condition of Surfacing	<u>S</u>
Description of observation: <u>MSS Surfacing work found in good Condition.</u>		
b)	Adequate Thickness of pavement layers constructed	<u>S</u>
Description of observation: <u>G.B - 200 mm W.B.M - 75 mm M.S.S - 20 mm</u>		
c)	Quality of Construction Material Used	<u>S</u>
Description of observation: <u>Good quality Crust material used</u>		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>NA</u>
Description of observation: <u>NA</u>		
e)	Compaction of flanks/ slope & raincuts	
Description of observation: <u>Flank work in progress</u>		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	<u>'S'</u>
b)	Condition of Vent Clearance	<u>'S'</u>
c)	Condition of railings/Slab/approach for Bridges	<u>'NA'</u>
Description of observation of CD works: <u>Found in good Condition</u>		
Remark if any:		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	<u>S</u>
---------------------------------------	----------

Name of Officer: CHANDRA SUGHAR AZAD

Designation: R.E.

22/06/21
Adm

22/06/21
(Signature)