

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: <i>Ghaghara PWD Road to Pakariya via Bahuban</i>		
Hazards: <i>Flood/Rain</i>		
Division: <i>Sitamarhi</i>	District:	Actual Length (in km): <i>3.176</i>
Damage Length (in km): <i>0.300</i>	Damages Location/Chainage:	
Name of Scheme/Programme:	<i>PDR</i>	
Status of Project:	Under Agreement / Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	<i>BT</i>
a)	Condition of Surfacing	<i>S</i>
Description of observation : <i>MSS Surfacing found in good Condition</i>		
b)	Adequate Thickness of pavement layers constructed	<i>S</i>
Description of observation : <i>Adequate thickness found</i>		
c)	Quality of Construction Material Used	<i>S</i>
Description of observation : <i>Good quality crust material used</i>		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	
Description of observation : <i>NA</i>		
e)	Compaction of flanks/ slope & raincuts	
Description of observation : <i>work in progress.</i>		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	<i>S</i>
b)	Condition of Vent Clearance	<i>S</i>
c)	Condition of railings/Slab/approach for Bridges	<i>NA</i>
Description of observation of CD works : <i>Found in good Condition.</i>		
Remark if any:		
Overall Rating		

Satisfactory (S) / Unsatisfactory (U)

'S'

Name of Officer: *CHANDRA SHEKHAR AZAD*

Designation:

23/6/21

23/6/21
(Signature)

23/06/21
AE