

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: *NH-17 Kanpur Phase In 17th*

Hazards: Flood/Rain

Division: *G. D. Wazir*

District: *G. D. Wazir*

Actual Length (in km): *4.76*

Damage Length (in km): *0.600*

Damages Location/Chainage:

Name of Scheme Programme:

IPR

Status of Project:

Under Agreement Out of Agreement

Sr. No.

Parameters to be Checked in Restoration work

Remarks (S/U)

1.

Pavement (BT/CT)

U-T

a)

Condition of Surfacing

S

Description of observation :

MSS Surfacing work found in good condition.

b)

Adequate Thickness of pavement layers constructed

S

Description of observation :

Inadequate thickness found

c)

Quality of Construction Material Used

S

Description of observation :

Good quality material used

d)

Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.

Description of observation :

'NA'

e)

Compaction of flanks/ slope & raincuts

S

Description of observation :

Found in good condition

2

Cross Drainage Structure

a)

Condition of head walls in Hume pipe culverts

NA

b)

Condition of Vent Clearance

NA

c)

Condition of railings/Slab/approach for Bridges

NA

Description of observation of CD works :

NA

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer: *CHANDRA SHEKHAR AZAD*

Designation: *E-12.*

23/6/21
(Signature)

23/06/21
AES