

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: <i>Majaulia chowk to chandi Rajwara Road</i>		
Hazards		Flood/Rain
Division: <i>Sitamarhi</i>	District: <i>Sitamarhi</i>	Actual Length (in km): <i>3.767</i>
Damage Length (in km): <i>0.207</i>	Damages Location/Chainage:	
Name of Scheme/Programme: <i>FDR</i>		
Status of Project: <i>Under Agreement</i> / <i>Out of Agreement</i>		
Sr. No.	Parameters to be Checked in Restoration work	Remarks: (S/U)
1.	Pavement (BT/CC) <i>BT</i>	
a)	Condition of Surfacing	<i>S</i>
Description of observation: <i>MSS Surfacing work found in good Condition.</i>		
b)	Adequate Thickness of pavement layers constructed	<i>S</i>
Description of observation: <i>Adequate thickness found</i>		
c)	Quality of Construction Material Used	<i>S</i>
Description of observation: <i>Good quality material used</i>		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	
Description of observation: <i>NA</i>		
e)	Compaction of flanks/ slope & raincuts	<i>S</i>
Description of observation: <i>Found in good Condition</i>		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	<i>S</i>
b)	Condition of Vent Clearance	<i>S</i>
c)	Condition of railings/Slab/approach for Bridges	<i>NA</i>
Description of observation of CD works: <i>Found in good Condition -</i>		
Remark if any:		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

'S'

Name of Officer: *CHANORA SHEKHAR AZAD*

Designation: *E.E*

Ch
23/06/21
(Signature)

23/06/21
A.D.