

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: *Sarba Khetol to Mangalpur Samra*

Hazards: Flood/Rain *Flood*

Division: *Bofha - I*

District: *Chhatisgarh*

Actual Length (in km): *9.00*

Damage Length (in km):

Damages Location/Chainage:

Name of Scheme/Programme: *MR-3054*

Status of Project: Under Agreement/Out of Agreement

Sr. No. Parameters to be Checked in Restoration work Remarks : (S/U)

1. Pavement (BT/CC)

a) Condition of Surfacing

5

Description of observation : *In 130 m length approximately 20 mm MSS done throughout*

b) Adequate Thickness of pavement layers constructed

Description of observation : *Only Pot Path with 150 mm II & 150 mm III done at and where required.*

c) Quality of Construction Material Used

Description of observation : *MSS quality material specification*

d) Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.

Description of observation : *No undulation.*

e) Compaction of flanks/ slope & raincuts

Description of observation : *No rain cuts*

2. Cross Drainage Structure

NA

a) Condition of head walls in Hume pipe culverts

b) Condition of Vent Clearance

c) Condition of railings/Slab/approach for Bridges

Description of observation of CD works :

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory (S)

Name of Officer: *Rana Bham Kumbh Singh*

Designation: *Executive Engineer.*

23.06.2024
(Signature)