

Particulars	Details of actual measurement				Contents of area
	No	L	B	D	
lot 4 final bill					
Name of work: Restoration					
Work of Road - damaged by					
flood 2020 from Diba Tola					
to Mahavada in Pilsahi Block					
Agency: Departmental					
Date of Measurement: 23-9-20					
Date of entry: 28-4-21					
Item (A): Supplying &					
filling of brickbat					
Complete job.					
B/F P-1 Item (A)					
Qty. = 188.16 M					
Item (B): Supplying &					
filling of rubbish					
Complete job.					
B/F P-1 Item (B)					
Qty. = 47.04 M					
<i>Rumar</i> 28-04-2021 A. E. Pilsahi <i>Rumar</i> 28-4-21 J.E					
<i>[Signature]</i> 30-4-21					

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
<u>Abstract of Cost</u>					
Item 1(A) - Supplying & filling of brick wall					
Complete job.					
B/F P-2 Item 1(A)					
Qty. = 188.16 M ³					
@ Rs 1546.00 / M ³ - Rs 290895 = 00					
Item 1(B) - Supplying & filling of rubble					
Complete job.					
B/F P-2 Item 1(B)					
Qty. = 47.04 M ³					
@ Rs 742.00 / M ³ - Rs 34904 = 00					
Total Rs 325799 = 00					


Add 1% for labour cost - Rs 3258 = 00


Add 12% for GST - Rs 39096 = 00

Total Rs 368153 = 00

Say Rs 368150 = 00

Kumar
28.04.2021
A.P.
Piprahi


28.4.21
J.E.


30.4.21