

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD		
Name of Scheme: Construction of Road from Burza Chowk NH 57 through Thakamohar to hankhudi Jorhat up to 6		
Hazards	Flood/Rain	
Division: Forbessang	District: Araria	Actual Length (in km): 7.45
Damage Length (in km): 0+020	Damages Location/Chainage: 400m	
Name of Scheme/Programme:	3054 FDR	
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	BT
a)	Condition of Surfacing	3
Description of observation :		
b)	Adequate Thickness of pavement layers constructed	3
Description of observation : GSB Grading - II 100 mm WBM Gr. III 75 mm M.S.S 20 mm 195 mm		
c)	Quality of Construction Material Used	3
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	N.A.
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	3
Description of observation :		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	
c)	Condition of railings/Slab/approach for Bridges	
Description of observation of CD works :		
Remark if any:		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory

Name of Officer

Bindu Rajal
Executive Engineer
R.W.D.
Regional Laboratory
Dibrugarh

24/06/21
A.E.

Designation

24/06/21
(Signature)