

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Phulkaha Amrohi PWD Road Middle School Amrohi to Podder Tola.		
Hazards	Flood/Rain Flood	
Division: Forbesgarh	District: Araria	Actual Length (in km): 1.67
Damage Length (in km): 0.166	Damages Location/Chainage: 0.8 Km and 1.05 Km	
Name of Scheme/Programme:		
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	S
Description of observation : At chainage 800m C.S.B, WBM Gr III & M.S.S. work done		
At chainage - 1.05 Km C.S.B and WBM Gr III work done, M.S.S. not done		
b)	Adequate Thickness of pavement layers constructed	S
Description of observation : At chainage 800m - C.S.B Gr II 100mm W.B.M Gr III 75mm M.S.S. 20		
At chainage 1.05 Km, C.S.B - 100mm + W.B.M Gr III - 75mm		
c)	Quality of Construction Material Used	S
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	NA
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	
Description of observation : Earth work in Flank in progress		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	NA
c)	Condition of railings/Slab/approach for Bridges	
Description of observation of CD works :		
Remark if any:		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S


Name of Officer:

Binod Rajak

Designation:

Executive Engineer
R.W.D. Regional Carb. Darbhanga


24/06/21
A.E.


24/06/21
(Signature)