

# INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

|                             |                                                                      |                                                   |
|-----------------------------|----------------------------------------------------------------------|---------------------------------------------------|
| Name of Scheme: -           | Areriza to Ghoghardiha                                               |                                                   |
| Hazards                     | Flood/Rain                                                           |                                                   |
| Division: Phulparas         | District: Madhubani                                                  | Actual Length (in km): 12.47                      |
| Damage Length (in km): 0.50 | Damages Location/Chainage: 12.00 Km to 12.50 Km.                     |                                                   |
| Name of Scheme/Programme:   |                                                                      |                                                   |
| Status of Project:          | Under Agreement <input checked="" type="checkbox"/> Out of Agreement |                                                   |
| Sr. No.                     | Parameters to be Checked in Restoration work                         | Remarks <input checked="" type="checkbox"/> (S/U) |
| 1.                          | Pavement (BT/CC) - BT                                                |                                                   |
| a)                          | Condition of Surfacing - Satisfactory                                |                                                   |

Description of observation :

|    |                                                   |     |
|----|---------------------------------------------------|-----|
| b) | Adequate Thickness of pavement layers constructed | YES |
|----|---------------------------------------------------|-----|

Description of observation :

|    |                                       |      |
|----|---------------------------------------|------|
| c) | Quality of Construction Material Used | Good |
|----|---------------------------------------|------|

Description of observation :

|    |                                                                                                                                                       |   |
|----|-------------------------------------------------------------------------------------------------------------------------------------------------------|---|
| d) | Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc. | — |
|----|-------------------------------------------------------------------------------------------------------------------------------------------------------|---|

Description of observation :

|    |                                        |             |
|----|----------------------------------------|-------------|
| e) | Compaction of flanks/ slope & raincuts | In Progress |
|----|----------------------------------------|-------------|

Description of observation :

|    |                                                 |    |
|----|-------------------------------------------------|----|
| 2  | Cross Drainage Structure                        |    |
| a) | Condition of head walls in Hume pipe culverts   | NA |
| b) | Condition of Vent Clearance                     |    |
| C) | Condition of railings/Slab/approach for Bridges |    |

Description of observation of CD works :

Remark if any:

Overall Rating

|                                                                           |              |
|---------------------------------------------------------------------------|--------------|
| <input checked="" type="checkbox"/> Satisfactory (S) / Unsatisfactory (U) | Satisfactory |
|---------------------------------------------------------------------------|--------------|

Name of Officer:

Ram Kumar Mishra.

Designation:

E.E R. Lab Gultarbag  
Patna

(Signature) 12/06/23