Abstract of cost for Restoration work of Basant Path (Ashogi Bazar) to Piprahi Punarwasr after flood 2020.

Sl. No.	Item of work	Unit	Quantity	Rate	Amount
1	Supplying & filling of brick bats with manual compaction ....do....do all complete job as per direction of E/I.				
	(a) Bricks bat	cum	140.7	1546.00	217522.20
	(b) Rubbish	cum	35.17	742.00	26096.14
			Total		243618.34
			Add 1% labour Cess		2436.18
			Add 12% GST		29234.20
			Grand Total		275288.72
			Say Rs		275280.00

5-4-21 J.E

Kumar 05.04.021 A.E.

6.4.21 E.E.

यह प्राक्कलन अधीक्षण अभियंता कार्य मंडल सीतामढ़ी द्वारा गठित जाँचदल (कार्यपालक अभियंता सीतामढ़ी) के जाँच प्रतिवेदन 254 / 29-1-21

Technically Approved for Rs 275280=00 (Rupees Two Lakh Seventy five thousand Two hundred Eighty) Only.

12/4/21

S.E.
R.W.D. (W) Circle
Sitamarhi

Scanned with CamScanner

Detailed Estimate of Restoration work of Basant Path (Ashogi Bazar) to Piprahi Punarwas after flood 2020.

sl no. 1	Supplying & filling of brick bats with manual compaction ....do....do all complete job as per direction of E/I.				
	chainage in M	**length in M**	**width in M**	**depth in M**	**Quantity in cum**
	0	10.00	3.80	0.50	19.00
		30.00	3.30	0.45	44.55
		17.00	3.40	0.30	17.34
	200	15.00	3.50	1.00	52.50
		12.00	3.20	0.60	23.04
		18.00	3.60	0.30	19.44
					175.87
(a)				Brick Bats 80%	140.70
(b)				Local Sand/ Rubbish 20%	35.17

J.E A.E. E.E

Scanned with CamScanner