

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
lot 4 final bill					
Name of Work: - Restoration work of Road damaged by flood 2020 from Tarwanwada to Kararid in Dummari Katarasari Block.					
Agency: - Departmental					
Date of Measurement: - 8-10-20					
Date of entry: - 6-5-21					
Item 1(A): - Supplying & filling of brick bats to breaches and damaged portion of road complete job.					
B/R P-1 Item 1(A)					
					13.63M

Item 1(B): - Supplying & filling of rubbish Complete job.

B/R P-1 Item 1(B)

Qty = 18.41M

Kumar
06.5.2021
A.E.

6-5-21

6-5-21

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	

Abstract of cost
 Item 1(A) :- Supplying
 & filling of bricks
 Complete job
 B/F P-2 Item 1(A)

Qty. = 13.63 M³

@ Rs 1546.00/M³ - Rs 113832.00

Item 1(B) :- Supplying
 & filling of rubble
 Complete job
 B/F P-2 Item 1(B)

Qty. = 18.41 M³

@ Rs 742.00/M³ - Rs 13660.00

Total Rs 127492.00

Add 1% labour cost - Rs 1275.00

Add 12% for GST - Rs 15299.00

Total Rs 1,44,066.00

Say Rs 1,44,066.00

Kumar
 6.5.21
 A.E.

Kumar
 6.5.21
 J.E.

Kumar
 6.5.21