

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Chakardaha Mil Chowk to Rewahi Parthraha Padha

Hazards: Flood/Rain Flood

Division: Forbesganj District: Araria Actual Length (in km): 18.50

Damage Length (in km): 0.200 Damages Location/Chainage:

Name of Scheme/Programme:

Status of Project: Under Agreement/Out of Agreement

Sr. No. Parameters to be Checked in Restoration work Remarks : (S/U)

1. Pavement (BT/CC)

a) Condition of Surfacing

S

Description of observation : G.S.B. & W.B.M. work done
M.S.S. not done

b) Adequate Thickness of pavement layers constructed

S

Description of observation : At chainage 7-60km length - 2x30=60m
At chainage 7-80 length - 20m
At chainage 8-60. length - 120m
G.S.B. 100mm
W.B.M. 75mm
Grit 175mm

c) Quality of Construction Material Used

S

Description of observation :

d) Whether free from any defects and Irregularity example-
Surface Cracks, Undulation, exposed aggregates in case of
CC Pavement, Poor workmanship, etc.

N.A

Description of observation :

e) Compaction of flanks/ slope & raincuts

S

Description of observation :

2 Cross Drainage Structure

a) Condition of head walls in Hume pipe culverts

b) Condition of Vent Clearance

c) Condition of railings/Slab/approach for Bridges

1
1
U
S

Description of observation of CD works :

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer: Bindu Rajal
Executive Engineer

Designation: R.W.D.
Regional Laboratory Darbhanga

25/06/21
A.E.

25/06/21
Signature