

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Narpatganj Mahthawa Main Road to Gopal Yadav House
Parrihar Nahar

Hazards: Flood/Rain Flood

Division: Forbesganj District: Araria Actual Length (in km): 5.84

Damage Length (in km): 0.100 Damages Location/Chainage: 960m

Name of Scheme/Programme:

Status of Project: Under Agreement/Out of Agreement

Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
---------	--	-----------------

1.	Pavement (BT/CC) <u>BT</u>	<u>S</u>
a)	Condition of Surfacing	

Description of observation : M.S.S. work not done.

b)	Adequate Thickness of pavement layers constructed	<u>S</u>
----	---	----------

Description of observation : G.S.B. grading II - 100 mm

W.B.M. grade III + 75 mm

175 mm

c)	Quality of Construction Material Used	<u>S</u>
----	---------------------------------------	----------

Description of observation :

d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>-</u>
----	---	----------

Description of observation :

e)	Compaction of flanks/ slope & raincuts	<u>S</u>
----	--	----------

Description of observation :

2	Cross Drainage Structure	<u>-</u>
---	--------------------------	----------

a)	Condition of head walls in Hume pipe culverts	<u>-</u>
----	---	----------

b)	Condition of Vent Clearance	<u>-</u>
----	-----------------------------	----------

c)	Condition of railings/Slab/approach for Bridges	<u>-</u>
----	---	----------

Description of observation of CD works :

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer: Bindu Rajak
Executive Engineer
R.W.D.

Designation: Regional Laboratory Darbhanga

25/06/21
A.E.

25/06/21
(Signature)