

INSPECTION REPORT FOR FLOOD/RAIN DAMAGE ROAD			
Name of Scheme: <u>L-050-101 to Chikni</u>			
Hazards: <u>Flood/Rain</u>			
Division: <u>Phulparas</u>	District: <u>Machilipatnam</u>	Actual Length (in km): <u>3.30 Km</u>	
Damage Length (in km): <u>0.20</u>	Damages Location/Chainage:		
Name of Scheme/Programme:			
Status of Project: <u>Under Agreement/Not of Agreement</u>			
Sr. No.	Parameters to be Checked in Restoration work		Remarks: (y/n)
1.	Pavement (BT/CC)		<u>BT</u>
a)	Condition of Surfacing		<u>Good</u>
Description of observation :			
b)	Adequate Thickness of pavement layers constructed		<u>NO</u>
Description of observation : <u>Thickness of G.III is 2 inch</u> <u>G.III is less than specification.</u>			
c)	Quality of Construction Material Used		<u>Good</u>
Description of observation :			
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.		<u>—</u>
Description of observation :			
e)	Compaction of flanks/ slope & raincuts		<u>In Progress</u>
Description of observation :			
2	Cross Drainage Structure		} <u>NA</u>
a)	Condition of head walls in Hume pipe culverts		
b)	Condition of Vent Clearance		
c)	Condition of railings/Slab/approach for Bridges		
Description of observation of CD works :			
Remark if any: <u>Thickness of G.III is less than specification.</u>			

Overall Rating

Satisfactory (S) ☒ Unsatisfactory (U)

Unsatisfactory

Name of Officer: Ram Kumar Mishra

Designation:

E.E. Road Gulzarbag
Patna

3/06/22
(Signature)