

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Central Chowk Bazar to Mahadelli -tola

Hazards: Flood/Rain

Division: Barnipatti District: Madhubani Actual Length (in km): 1.320 km

Damage Length (in km): 0.070 km Damages Location/Chainage: 0.100, 0.251 km

Name of Scheme/Programme: Restoration

Status of Project: Under Agreement/Out of Agreement

Sr. No. Parameters to be Checked in Restoration work Remarks : (S/U)

1. Pavement (BT/CC)

a) Condition of Surfacing S

Description of observation :

b) Adequate Thickness of pavement layers constructed S

Description of observation :

c) Quality of Construction Material Used S

Description of observation :

d) Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc. —

Description of observation :

e) Compaction of flanks/ slope & raincuts —

Description of observation :

2 Cross Drainage Structure

a) Condition of head walls in Hume pipe culverts —

b) Condition of Vent Clearance —

c) Condition of railings/Slab/approach for Bridges —

Description of observation of CD works :

Remark if any:

Damage Portion after work surface is good condition

Overall Rating

Satisfactory (S) / Unsatisfactory (U) S

Name of Officer: Sri Kant Prasad

Designation: E-E

24/06/21

24/6/2021

(Signature)