

INSPECTION REPORT FOR FLOOD/RAIN DAMAGE ROAD

Name of Scheme: <u>Bharhar to Ghosha (1st)</u>		
Hazards	Flood/Rain	
Division: <u>Bonepath</u>	District: <u>Madhubani</u>	Actual Length (in km): <u>6.998</u>
Damage Length (in km): <u>0.289 km</u>	Damages Location/Chainage: <u>0.56, 1.610, 2.549, 3.100, 4.638 km</u>	
Name of Scheme/Programme:	Restoration	
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	S
Description of observation :		
b)	Adequate Thickness of pavement layers constructed	S
Description of observation :		
c)	Quality of Construction Material Used	S
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	—
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	—
Description of observation :		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	—
b)	Condition of Vent Clearance	—
c)	Condition of railings/Slab/approach for Bridges	—
Description of observation of CD works :		
Remark if any:		
Damage Portion after Work done Surface good Condition		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Sri Kant Prasad
Name of Officer:

Designation: E.E.

24/06/21

24/6/2021
(Signature)