

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: <u>Bhagat Pokhar to Kalidas Dih</u>		
Hazards	Flood/Rain	
Division: <u>Benifatti</u>	District: <u>Madhubani</u>	Actual Length (in km): <u>2.352</u>
Damage Length (in km): <u>0.054</u>	Damages Location/Chainage: <u>1-132 km, 1-298, 1-362, 1-617 km</u>	
Name of Scheme/Programme:	<u>Restoration</u>	
Status of Project:	Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	<u>S</u>
Description of observation :		
b)	Adequate Thickness of pavement layers constructed	<u>S</u>
Description of observation :		
c)	Quality of Construction Material Used	<u>S</u>
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>NO</u>
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	<u>NO</u>
Description of observation :		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	
c)	Condition of railings/Slab/approach for Bridges	
Description of observation of CD works :		
Remark if any: <u>after work</u> <u>Flood Damage surface portions in good condition</u>		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Sri Kant Prasad
Name of Officer:

Designation: E-E

23/06/21
(Signature)

23/06/21 AE