

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD		
Name of Scheme: <u>Jhilkha To Balarahi</u>		
Hazards	Flood/Rain	
Division: <u>Bonipatti</u>	District: <u>Madhubani</u>	Actual Length (in km): <u>3.204 km</u>
Damage Length (in km): <u>0.057 km</u>	Damages Location/Chainage: <u>0.750, 1.169, 1.221, 1.310, 1.450</u>	
Name of Scheme/Programme: <u>Restoration</u>		
Status of Project: <u>Under Agreement/Out of Agreement</u>		
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	<u>S</u>
Description of observation :		
b)	Adequate Thickness of pavement layers constructed	<u>S</u>
Description of observation :		
c)	Quality of Construction Material Used	<u>S</u>
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>-</u>
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	<u>-</u>
Description of observation :		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	<u>-</u>
b)	Condition of Vent Clearance	<u>-</u>
C)	Condition of railings/Slab/approach for Bridges	<u>-</u>
Description of observation of CD works :		
Remark if any:		
<u>Damage portion after work surface is good condition</u>		
Overall Rating		

Satisfactory (S) / Unsatisfactory (U)

S

Sri Kant Prasad
Name of Officer:

Designation: E-E

24/06/24

24/6/24
(Signature)