

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD			
Name of Scheme:		chowki Heat to Nayatola chowki	
Hazards		Flood/Rain	
Division :	Barsei	District:	Katihar
Damage Length (in km):	0.118	Actual Length (in km):	1.491
Name of Scheme/Programme:		FDR	
Status of Project:		Under Agreement/Out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work		Remarks : (S/U)
1.	Pavement (BT/CC)		BT
a)	Condition of Surfacing		S
Description of observation :			
No defect			
b)	Adequate Thickness of pavement layers constructed		S
Description of observation :			
PMC - 20 mm thickners,			
c)	Quality of Construction Material Used		S
Description of observation :			
Good.			
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.		S
Description of observation :			
No any defect,			
e)	Compaction of flanks/ slope & raincuts		S
Description of observation :			
flank maintaind,			
2	Cross Drainage Structure		
a)	Condition of head walls in Hume pipe culverts		—
b)	Condition of Vent Clearance		—
c)	Condition of railings/Slab/approach for Bridges		—
Description of observation of CD works :			
No Provision in this scheme			
Remark if any:			

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	Satisfactory (S)
---------------------------------------	------------------

Name of Officer: Mahesh Pd Gupta.
 Designation: EE, RWD, Regional Lab
 Patna

(Signature)
 25/6/21

(Signature)
 25/06/2021