

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD		
Name of Scheme: L 046 - T 03 To Khorabari (Track-29)		
Hazards	Flood/Rain	
Division: Manihari	District: Katihar	Actual Length (in km): 1.213
Damage Length (in km): 0.540	Damages Location/Chainage: -	
Name of Scheme/Programme:	FDR	
Status of Project:	Under Agreement/Out of Agreement - out of Agreement	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	S
Description of observation : BT work		
b)	Adequate Thickness of pavement layers constructed	
Description of observation : 20 mm Mix seal surface - Satisfactory		
c)	Quality of Construction Material Used	S
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement , Poor workmanship, etc.	S
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	-
Description of observation : No provision in the scheme		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	-
b)	Condition of Vent Clearance	-
c)	Condition of railings/Slab/approach for Bridges	-
Description of observation of CD works : No provision in the scheme		
Remark if any:		
Overall Rating		

Satisfactory (S) / Unsatisfactory (U)	S
---------------------------------------	---

Name of Officer: Ram Prabesh Jais

Designation: T.A RWD
Works Circle Siwan

(Signature) *Ram.6.21*

24/6/21
AC