

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD		
Name of Scheme: Badi Hanswar Babulal kishi house to Karwar Dhar .		
Hazards	Flood/Rain	
Division : Manihari	District: Katihar	Actual Length (in km): 3.00 km
Damage Length (in km): 0.760	Damages Location/Chainage: -	
Name of Scheme/Programme:	FDR	
Status of Project:	Under Agreement/Out of Agreement Out of Agreement .	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	S
Description of observation :		
b)	Adequate Thickness of pavement layers constructed	-
Description of observation : In good condition, Mix seal surfacing (20 mm) - satisfactory.		
c)	Quality of Construction Material Used -	S
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement , Poor workmanship, etc.	S
Description of observation :		
e)	Compaction of flanks/ slope & raincuts	-
Description of observation : No provision in this scheme .		
2	Cross Drainage Structure	
a)	Condition of head walls in Hume pipe culverts	-
b)	Condition of Vent Clearance	-
c)	Condition of railings/Slab/approach for Bridges	-
Description of observation of CD works : No provision of CD work in this scheme .		
Remark if any:		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)	S
---------------------------------------	---

Name of Officer: Ram Prabesh Saw

Designation: T.A , RWD
Work circle Siwan.

ph
23.6.21
(Signature)

Wd.
A.E.
23/6/21