

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: MMGSY Gogsi Jhil To Lahi Tola

Hazards Flood/Rain

Division: Manihari District: Katihar Actual Length (in km): 1.655

Damage Length (in km): 0.828 Damages Location/Chainage: -

Name of Scheme/Programme: FDR

Status of Project: Under Agreement/Out of Agreement Out of Agreement

Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	
a)	Condition of Surfacing	S

Description of observation :
BT work

b) Adequate Thickness of pavement layers constructed —

Description of observation :
20 mm Mix seal surface — Satisfactory

c) Quality of Construction Material Used S

Description of observation :

d) Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc. S

Description of observation :

e) Compaction of flanks/ slope & raincuts —

Description of observation :
NO provision in this scheme

2 Cross Drainage Structure

a) Condition of head walls in Hume pipe culverts —

b) Condition of Vent Clearance —

c) Condition of railings/Slab/approach for Bridges —

Description of observation of CD works :

NO provision in the scheme

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer: Ram Prabesh Saw

Designation: TA, RWD
works circle, Sways

(Signature)
23/6/21

23/6/21
AC