

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

| | | |
|---|--|-------------------------------------|
| Name of Scheme: <u>Nawabganj Mansahi Leo Road to Santhal Tola</u> | | |
| Hazards | Flood/Rain | |
| Division: <u>Manihari</u> | District: <u>Katihar</u> | Actual Length (in km): <u>1.227</u> |
| Damage Length (in km): <u>0.541</u> | Damages Location/Chainage: <u>-</u> | |
| Name of Scheme/Programme: | <u>FDR</u> | |
| Status of Project: | Under Agreement/Out of Agreement <u>Out of Agreement</u> | |
| Sr. No. | Parameters to be Checked in Restoration work | Remarks : (S/U) |
| 1. | Pavement (BT/CC) | |
| a) | Condition of Surfacing | <u>S</u> |
| Description of observation : | | |
| <u>BT work</u> | | |
| b) | Adequate Thickness of pavement layers constructed | |
| Description of observation : | | |
| <u>20 MM Mix seal surface — Satisfactory</u> | | |
| c) | Quality of Construction Material Used | <u>S</u> |
| Description of observation : | | |
| d) | Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement , Poor workmanship, etc. | <u>S</u> |
| Description of observation : | | |
| e) | Compaction of flanks/ slope & raincuts | <u>-</u> |
| Description of observation : | | |
| <u>No provision in the scheme</u> | | |
| 2 | Cross Drainage Structure | |
| a) | Condition of head walls in Hume pipe culverts | <u>-</u> |
| b) | Condition of Vent Clearance | <u>-</u> |
| c) | Condition of railings/Slab/approach for Bridges | <u>-</u> |
| Description of observation of CD works : | | |
| <u>No provision in the scheme .</u> | | |
| Remark if any: | | |

Overall Rating

| | |
|---------------------------------------|----------|
| Satisfactory (S) / Unsatisfactory (U) | <u>S</u> |
|---------------------------------------|----------|

Name of Officer:

Ram Prabesh Sahu

Designation:

T.A RWD
Work Circle Siwan

R
25.6.21
(Signature)

25/6/21
AE