

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: PAKARI CHAUK TO RAMPUR GANGAULI		
Hazards		Flood/Rain
Division: RWD(W) SITAPUR	District: SITAPUR	Actual Length (in km): 4.38 km.
Damage Length (in km): 0.250 km.	Damages Location/Chainage: 1.200 km to 1.450 km.	
Name of Scheme/Programme:		FDR
Status of Project:		Under Agreement/Out of Agreement
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC) B.T	
a)	Condition of Surfacing	S
Description of observation : MSS Surfacing found in good Condition		
b)	Adequate Thickness of pavement layers constructed	'S'
Description of observation : Adequate thickness found		
c)	Quality of Construction Material Used	S
Description of observation : Good quality Material used		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	
Description of observation : NA		
e)	Compaction of flanks/ slope & raincuts	
Description of observation : work in Progress		
2	Cross Drainage Structure	NA
a)	Condition of head walls in Hume pipe culverts	NA
b)	Condition of Vent Clearance	NA
c)	Condition of railings/Slab/approach for Bridges	NA
Description of observation of CD works : NA		
Remark if any:		
Overall Rating		
Satisfactory (S) / Unsatisfactory (U)		'S'

Name of Officer: CHANDRA SAKHAR AZAD
Designation: E.E.

25/06/21
A.E.

25/06/21
(Signature)