

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: Surgahija to Bhatsulla
 Hazards: Flood/Rain
 Division: Sitamarhi District: Sitamarhi Actual Length (in km): 3.490 km
 Damage Length (in km): 0.560 km Damages Location/Chainage: 0.08 km to 0.640 km
 Name of Scheme/Programme: FDR

Status of Project: Under Agreement/Out of Agreement

Sr. No. 1. Parameters to be Checked in Restoration work Pavement (BT/CC) BT Remarks: (S/U) S

a) Condition of Surfacing S

Description of observation: M/S Surfacing found in good condition

b) Adequate Thickness of pavement layers constructed S

Description of observation: Adequate thickness found

c) Quality of Construction Material Used S

Description of observation: Good quality of Material used

d) Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.

Description of observation: NA

e) Compaction of flanks/ slope & raincuts

Description of observation: work in progress

2 Cross Drainage Structure

a) Condition of head walls in Hume pipe culverts

b) Condition of Vent Clearance NA

c) Condition of railings/Slab/approach for Bridges

Description of observation of CD works:

NA

Remark if any:

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer: CHANDRA SHEKHAR RAO

Designation: E.E.

25/06/21
A.E.

25/06/21
(Signature)