

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD			
Name of Scheme: <u>Chauki - Kachora</u>		Flood/Rain	
Division: <u>Barsoi</u>	District: <u>Katihar</u>	Actual Length (in km): <u>17.250</u>	
Damage Length (in km): <u>1.009</u>	Damages Location/Chainage:		
Name of Scheme/Programme: <u>FDR</u>		Status of Project: <u>Under Agreement/Out of Agreement</u>	
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)	
1.	Pavement (BT/CC)		
a)	Condition of Surfacing	<u>S</u>	
Description of observation : <u>No defect</u>			
b)	Adequate Thickness of pavement layers constructed	<u>S</u>	
Description of observation : <u>PMC - 20mm thickness.</u>			
c)	Quality of Construction Material Used	<u>S</u>	
Description of observation : <u>Good.</u>			
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>S</u>	
Description of observation : <u>No defect</u>			
e)	Compaction of flanks/ slope & raincuts	<u>S</u>	
Description of observation : <u>at some places, Raincut- found. needs repair</u>			
2	Cross Drainage Structure		
a)	Condition of head walls in Hume pipe culverts		
b)	Condition of Vent Clearance		
c)	Condition of railings/Slab/approach for Bridges		
Description of observation of CD works : <u>No provision in the scheme.</u>			
Remark if any:			

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

Satisfactory (S)

Name of Officer:

Designation:

Mahesh Pd Gupta

E.E, RWD Regional Laboratory
Putnra

25/06/2022
(Signature) EE

25/06
AC