

INSPECTION REPORT FOR FLOOD /RAIN DAMAGE ROAD

Name of Scheme: <u>Bhokaha to Ramdaspur</u>		
Hazards	Flood/Rain	
Division: <u>Madhura</u>	District: <u>Saran</u>	Actual Length (in km): <u>8.24</u>
Damage Length (in km): <u>0.490</u>	Damages Location/Chamage	
Name of Scheme/Programme: <u>PM USY</u>		
Status of Project: <u>Under Agreement/Out of Agreement</u>		
Sr. No.	Parameters to be Checked in Restoration work	Remarks : (S/U)
1.	Pavement (BT/CC)	<u>S</u>
a)	Condition of Surfacing	<u>S</u>
Description of observation :		
b)	Adequate Thickness of pavement layers constructed	<u>S</u>
Description of observation :		
c)	Quality of Construction Material Used	<u>S</u>
Description of observation :		
d)	Whether free from any defects and Irregularity example- Surface Cracks, Undulation, exposed aggregates in case of CC Pavement, Poor workmanship, etc.	<u>-</u>
Description of observation :		
e)	Compaction of flanks/ slope & rainents	<u>S</u>
Description of observation :		
2	Cross Drainage Structure	<u>-</u>
a)	Condition of head walls in Hume pipe culverts	
b)	Condition of Vent Clearance	
c)	Condition of railings/Slab/approach for Bridges	
Description of observation of CD works: <u>N.A</u>		
Remark if any: <u>Work done overall was found satisfactory.</u>		

Overall Rating

Satisfactory (S) / Unsatisfactory (U)

S

Name of Officer:

KUMAR RAKESH

Designation:

तकनीकी सलाहकार
ग्रामीण कार्य विभाग
कार्य अंचल, पटना

24/6/21
AE

(Signature)

24.06.21