

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- *Oryan vibhaleys*

2 Name of Block/Road :- *minchpur / mustafaganj pvd rd to charnal path*

(A) For Road:

1. Damage Location/Chainage :- *0.001 km, 0.090 km*

2. Damage Length :- *0.1626 km*

3. Nature of Damage :-

4. Details of Restoration Works :-

(i) Material being used in Restoration works:- *new betts*

(ii) Equipment's/Tools being used in Restoration works:- *Tractor*

(iii) Procedure taken up in Restoration works:

(iv) Restored Length :-

(B) For Bridge:

1. Damage Location/Chainage :-

2. Damage Length :-

3. Nature of Damage :-

4. Details of Restoration Works :-

(i) Material being used in Restoration works:-

(ii) Equipment's/Tools being used in Restoration works:-

(iii) Procedure taken up in Restoration works:-

(iv) Restored Length :-

Signature of JE/AE/EE

[Signature]
Signature

(Name of Inspection)

GE

RWD mustafaganj Geft -1


GENERAL ABSTRACT

Name of Road	mustafaganj pwd rd to Chakmal path	
District	Muzaffarpur	
Block	Minapur	
Division	Muzaffarpur East-2	
Length of Road (in Km)	2.300 Km	
Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	9.165
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	9.165
TOTAL COST OF PROJECT IN LACS =		9.165


Say 9.17 lac


11/1/21

JE
RWD



11/01/21

AE
RWD


11/1

EE
RWD

Technically approved for Rs 9.17 lac.
(Rupees Nine lac seventeen thousand only)


13-1-21
SE

RWD work circle
muzaffarpur