

कार्यपालक अभियंता का कार्यालय

ग्रामीण कार्य विभाग

कार्य प्रमंडल सोनपुर

पत्रांक.....142..... सोनपुर, दिनांक.....31/2/2021.....

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल सोनपुर।

सेवा में,

नोडल पदाधिकारी (3054),
ग्रामीण कार्य विभाग
बिहार, पटना।

विषय:- बिहार ग्रामीण पथ अनुरक्षण निधि-2018 के तहत स्वीकृत योजना में
आवंटन उपलब्ध कराने के संबंध में।


महाशय,

उपर्युक्त विषयक ग्रामीण कार्य विभाग, कार्य प्रमंडल सोनपुर के अन्तर्गत बिहार
ग्रामीण पथ अनुरक्षण निधि-2018 के तहत स्वीकृत योजना के क्रियान्वयन हेतु आवंटन की
मांग विहित प्रपत्र में तैयार कर भेजी जा रही है।

अतः अनुरोध है कि उपर्युक्त योजना में आवंटन उपलब्ध कराने की कृपा की
जाये।

अनु०:-उपयोगिता प्रमाण-पत्र।

विश्वासभाजन


कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल सोनपुर
31/2/21

FORM GER 19-A

(See Government of India's Decision (I) below Rule-150
Form of Utilization Certificate up to the month of **February-2021**
PIU:- E.E.,R.W.D. Works Division Sonapur.

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in lacs Rs.)	Amount Received (in lac Rs.)	Particulars
1	2	3	4	5
1	Construction of Rural Roads Under Bihar Rural Road Maintenance Policy 2018		1978.74652	Certified that out of Rs 1978.74652 lakh received during the years 2020-21 in favour of E.E.R.W.D. works division Sonapur a sum of Rs 1865.72190 Lakh has been utilized for the purpose of Bihar Rural Road Maintenance Policy 2018 Scheme as given in the margin for which it was sanctioned and that the balance of Rs 113.02462 Lakh remaining unutilized at the end of the period under report.

Certified that I have satisfied that the condition of which the grants-in-aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually for the purpose for which it was sanctioned.

Kind of Checks:-

- Words have been supervised by Executive/superintending Engineer.
 - Periodical inspection has been conducted by Executive Engineer/ superintending Engineer.
 - Construction material has been tested.
 - Measurements have been recorded in the MBS and test conducted by the Assistant Engineer/ Executive Engineer.
 - All other nodal formalities have been observed.
- 3 physical Progress achieved-
- Construction of Road Works.
 - Construction of CD works

D.A.O

R.W.D. Works Division Sonapur.

EXECUTIVE ENGINEER

R.W.D. Works Division Sonapur.

Requisition Formate for Scheme Head - MR-3054 Under Bihar Rural Road Maintenance Policy 2018 (In Rectification and surface Renewal)

Division Name:- Rural Works Department, Works Division- Sonpur

Sl.No	Package No	Name of Road	Project ID as per MIS	Administrative Approval (AA)	Agreement Amount (in Lac)		Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in Km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in %	Previous Total Allocated Amount (in Lac)	Upto date expenditure as per MIS (in Lac)	Requisition against Work Done (in Lac)
					Length (in Km.)	Amount (in Lac)								
1	RM/SA/SON/20/002	Darbela - Balahiya	NEA220001793	5976 & 30.10.2019	3.890	145.748	16.07.2021	-	1735.00	25.00	5.05	0.00	0.00	0.00
2		Dighwara Bheldi Road			4.350	161.036			2758.00	25.00	5.03	0.00	0.00	99.98500
		Bishambharpur - Sarphu via Baidichupara	NEA220001793		2.700	101.147			1886	25.02	5.04	38.33400	38.33400	25.5570
		Khujauli to Sutihar Via Mahesla Khiklu	31306202170											
TOTAL														125.54200

(Signature)
D.A.O

R.W.D Works Div- Sonpur

(Signature)
Executive Engineer
R.W.D Works Div- Sonpur
14/12/21

Date	Time	Section	Length	Bumps	Speed	OR	IRI.TEGORY	Latitude	ongitude	Event
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD		
2/2/21	22:15:20	6	0.1	240	20.2	2400	2858	G	25.82065	84.95699 Normal
2/2/21	22:15:20	6	0.1	220	30.3	2200	2631	G	25.82147	84.95736 Normal
2/2/21	22:15:20	6	0.1	190	30.3	1900	2290	G	25.82224	84.95793 Normal
2/2/21	22:15:55	6	0.1	240	40.4	2400	2858	G	25.82301	84.95848 Normal
2/2/21	22:16:0	6	0.1	190	40.4	1900	2290	G	25.81918	84.95707 Normal
2/2/21	22:16:0	6	0.1	220	40.4	2200	2631	G	25.81839	84.95684 Normal
2/2/21	22:16:0	6	0.1	210	40.4	2100	2518	G	25.81738	84.95609 Curve
2/2/21	22:16:28	6	0.1	190	10.1	1900	2290	G	25.81701	84.957 Normal
2/2/21	22:17:0	6	0.1	190	30.3	1900	2290	G	25.81637	84.95764 Normal
2/2/21	22:17:6	6	0.1	170	30.3	1700	2063	G	25.81556	84.9581 Curve
2/2/21	22:17:6	6	0.1	240	40.4	2400	2858	G	25.81501	84.95892 Normal
2/2/21	22:17:6	6	0.1	170	50.5	1700	2063	G	25.81457	84.95976 Normal
2/2/21	22:17:6	6	0.1	160	40.4	1600	1950	G	25.81412	84.96076 Normal
2/2/21	22:17:41	6	0.1	200	40.4	2000	2404	G	25.8138	84.96163 Culvert
2/2/21	22:17:41	6	0.1	220	30.3	2200	2631	G	25.81392	84.96268 Normal
2/2/21	22:18:0	6	0.1	190	40.4	1900	2290	G	25.81404	84.9636 Normal
2/2/21	22:18:0	6	0.1	190	40.4	1900	2290	G	25.81419	84.96465 Normal
2/2/21	22:18:16	6	0.1	200	40.4	2000	2404	G	25.81429	84.96562 Normal
2/2/21	22:18:16	6	0.1	240	40.4	2400	2858	G	25.81448	84.9667 Culvert
2/2/21	22:18:16	6	0.1	200	30.3	2000	2404	G	25.81511	84.96727 Normal
2/2/21	22:18:52	6	0.1	230	20.2	2300	2745	G	25.81595	84.96763 Curve
2/2/21	22:19:0	6	0.1	310	20.2	3100	3654	G	25.81641	84.96855 Curve
2/2/21	22:19:27	6	0.1	360	10.1	3600	3350	G	25.81703	84.96926 Normal
2/2/21	22:20:2	6	0.1	230	10.1	2300	2745	G	25.81794	84.9703 Normal
2/2/21	22:20:2	6	0.1	220	20.2	2200	2631	G	25.81864	84.97111 Normal
2/2/21	22:20:38	6	0.1	180	20.2	1800	2177	G	25.8194	84.97162 Normal
2/2/21	22:20:38	6	0.1	200	30.3	2000	2404	G	25.82023	84.9719 Normal
2/2/21	22:21:0	6	0.1	220	30.3	2200	2631	G	25.82112	84.97227 Curve
2/2/21	22:21:13	6	0.1	240	30.3	2400	2858	G	25.82133	84.9732 Normal
2/2/21	22:21:13	6	0.1	240	20.2	2400	2858	G	25.82117	84.97419 Normal
2/2/21	22:21:48	6	0.1	330	20.2	3300	3881	G	25.8216	84.97492 Culvert
2/2/21	22:22:0	6	0.1	280	20.2	2800	3313	G	25.82236	84.97551 Normal
2/2/21	22:22:0	6	0.1	240	30.3	2400	2858	G	25.82329	84.97564 Normal
2/2/21	22:22:23	6	0.1	270	30.3	2700	3199	G	25.82413	84.97588 Normal
2/2/21	22:22:23	6	0.1	250	30.3	2500	2972	G	25.82494	84.97633 Normal
2/2/21	22:22:23	6	0.1	280	20.2	2800	3313	G	25.82554	84.9771 Normal
2/2/21	22:23:34	6	0.1	330	0	3300	3881	G	25.82527	84.97779 Speed Breaker

10/10/21

10/10/21



2/2/21	22:24:9	6	0.1	300	0	3000	8540 G	25.82468	84.97827	Normal
2/2/21	22:24:9	6	0.1	250	30.3	2500	2972 G	25.82441	84.97918	Normal
2/2/21	22:24:45	6	0.1	260	30.3	2600	3086 G	25.82397	84.98005	Normal
2/2/21	22:24:45	6	0.1	200	30.3	2000	2404 G	25.82338	84.98081	Curve
2/2/21	22:25:0	6	0.1	220	40.4	2200	2631 G	25.82284	84.982	Culvert



Lab Job number :6

Date :02-02-2021

Name of Customer :ABHAY CONSTRUCTION

Name of Work/ Road :Dighwara Bheldi Road

Bishambharpur-Sangha via Balichapra

Sr.no	Location of Corrected U.I test(in km) value(mm/km)	Road category
		2858 G
2	0.1	2631 G
3	0.2	2290 G
4	0.3	2858 G
5	0.4	2290 G
6	0.5	2631 G
7	0.6	2518 G
8	0.7	2290 G
9	0.8	2290 G
10	0.9	2063 G
11	1	2858 G
12	1.1	2063 G
13	1.2	1950 G
14	1.3	2404 G
15	1.4	2631 G
16	1.5	2290 G
17	1.6	2290 G
18	1.7	2404 G
19	1.8	2858 G
20	1.9	2404 G
21	2	2745 G
22	2.1	3654 G
23	2.2	3350 G
24	2.3	2745 G
25	2.4	2631 G
26	2.5	2177 G
27	2.6	2404 G
28	2.7	2631 G
29	2.8	2858 G
30	2.9	2858 G
31	3	3881 G
32	3.1	3313 G
33	3.2	2858 G
34	3.3	3199 G
35	3.4	2972 G
36	3.5	3313 G
37	3.6	3881 G
38	3.7	3540 G
39	3.8	2972 G
40	3.9	3086 G
41	4	2404 G
42	4.1	2631 G
43	4.2	2408 G


46

46



File :D:\New folder\02022307.Xls. Section No. :6. Eqr .test

Name of Customer :Abhay construction, Name of Work/ Road :Dighwara Bheldi road-Bishambharpur Sangha Via



Yr/

02/07/2023

02/07/2023
02/07/2023
02/07/2023