

GENERAL ABSTRACT

Name of Road Daini Math Gariba Katohari Bazar to Dharampur

District East Champaran

Block Kalyanpur

Division Chakia

Length of Road (in Km)

7.928 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Excavation in Soil using Hydraulic Excavator	0.000
2	Bricks Bats	11.785
3	Sand Filling	0.000
4	Sand bag	0.000
5	Bamboo Piles	0.000
6	H.P.	0.000
TOTAL COST OF PROJECT IN LACS =		11.785

JE
25.08.2020

JE
RWD

AE
RWD

EE
RWD

Post facto

T.A. ~~75~~ is accorded for Rs. 11,78,500 = *Rs*

(..... crore. *Eleven* lacs. *Seventy Eight* thousand

Five hundred only.

Mun
19.12.20
S.E. (R.W.)
works C
Motihari

Dani
29-12-20

कार्यपालक अभियंता का कार्यालय ग्रामीण कार्य विभाग, कार्य प्रमण्डल पकड़ीदयाल।

पत्रांक: 1672 अनु0 / चकिया, दिनांक: 28 / 12 / 2020

प्रेषक

कार्यपालक अभियन्ता
ग्रामीण कार्य विभाग
कार्य प्रमण्डल-पकड़ीदयाल।

सेवा में,

अधीक्षण अभियन्ता,
ग्रामीण कार्य विभाग,
कार्य अंचल, मोतिहारी।

विषय- वर्ष-2020 के बाढ़ में क्षतिग्रस्त पथों को (मोटरबुल) यातायात बहाल करने हेतु कराये गये कार्यों की जाँच के संबंध में।

प्रसंग- मु0अ0-4 (मु0) विविध (कार्य)-23-40/2016- 2789 पटना, दिनांक-21.08.2020 एवं भवदीय कार्यालय आदेश ज्ञापांक-1344, दिनांक-28.08.2020


महाशय,

उपरोक्त विषयक एवं प्रासंगिक पत्र के अनुपालन में कार्य प्रमण्डल, चकिया द्वारा उपलब्ध कराये गए मोटरबुल पथों की सूची में अंकित पथों का अद्योहस्ताक्षरी तथा सहायक अभियन्ता एवं कनीय अभियन्ता के द्वारा निरीक्षण किया गया। निरीक्षण के दौरान कार्य प्रमण्डल, चकिया द्वारा प्रतिवेदित सभी पथों में मोटरबुल का कार्य कराया गया है एवं वर्तमान में यातायात चालू है।


सादर सूचनार्थ एवं अग्रेतर कार्रवाई हेतु समर्पित।

अनु0-निरीक्षण किये गए पथों की सूची।

विश्वासभाजन,


कनीय अभियन्ता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल पकड़ीदयाल



सहायक अभियन्ता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल पकड़ीदयाल


कार्यपालक अभियन्ता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, पकड़ीदयाल।

ज्ञापांक- 1672

दिनांक- 28/12/20

प्रतिलिपि-कार्यपालक अभियन्ता, ग्रामीण कार्य विभाग, कार्य प्रमण्डल, चकिया को सूचनार्थ समर्पित।


कार्यपालक अभियन्ता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल पकड़ीदयाल।

Sl. No.	Div.	Block Name	Area	Scheme	Road Status	Is Agreed? (Yes/No)	Length of Damage Part Due to Flood	Water Restoration (Days)	Remarks	Start Location	End Location	Est. Length	Est. Area
1	Chakra	Pipla N.H. 28 to Kalyanpur REO Road	Chakra	HR	Completed	Yes	9.1	1	Restoration work in progress.	26.489275	26.487906	84.981854	84.981854
2	Chakra	Ram Janki Chowk Sitakund to Bedban Madhuban Mahila Tola	Chakra	PMGSY(SC)	Completed	Yes	2.401	0.025	One Breach found at Ch 1050 M.	26.511473	26.510482	85.001754	85.001754
3	Chakra	Dekha Bandh to Ajit Singh ke Tola Tak	Keshariya	PMGSY(Gen)	Completed	Yes	1.15	1.15	Submerged in flood water of Gandak River	26.310427	26.310482	84.83154	84.83154
4	Chakra	Vrindavan Road se Kalyanpur path	Kalyanpur	HR	Completed	Yes	7.5	7.5	Cut/Damaged due to Heavy Rain	26.401555	26.401568	84.953742	84.953742
5	Chakra	Champan Tatbandh to Bariya	Keshariya	PMGSY(SC)	On Going	No	1.415	1.415	Submerged in flood water of Gandak River	26.312441	26.312441	84.820148	84.820148
6	Chakra	NH28 Gili Tola se Raja Ram Tak	Keshariya	PMGSY(Gen)	Completed	Yes	2.155	2.155	Cut/Damaged due to Heavy Rain	26.383692	26.383692	84.772928	84.772928
7	Chakra	Diliya Nadi Hanuman Mandir se Dr. Umesh Rai hotel hue to P.W.D. Bandh	Keshariya	PMGSY(SC)	On Going	No	1.832	1	Ch-300 M to 1800 M, Submerged in flood water.	26.302064	26.302064	84.85044	84.85044
8	Chakra	"Bahura Chowk se Narayanpur Path"	Kalyanpur	HR	Completed	Yes	7.1	7.1	200 M Road Submerged in Flood	26.380576	26.378107	84.914506	84.914506
9	Chakra	Dainimath - Gariba	Kalyanpur	PMGSY	Completed	Yes	7.3	7.3	Road Crust Damage due to heavy rain and cut by villagers to pass rain water away from habitation area.	26.423268	26.409943	84.863664	84.863664
10	Chakra	Kesaria - Bathna	Keshariya	PMGSY	Completed	Yes	5.712	5.712	Cut/Damaged due to Heavy Rain & Partially Submerged in Flood	26.330706	26.330706	84.88324	84.88324
11	Chakra	PURAINA TO BANPARUA	Keshariya	PMGSY(SC)	Completed	Yes	0.025	7	A Breach 2X10 M Span Bridge Constructed by RLDA about 20 years ago situated in this Road at Ch-1000 M wash	26.435611	26.435611	84.796478	84.796478
12	Chakra	SH 74 to Barhi Tola	Keshariya	PMGSY(Gen)	On Going	No	1.811	1	Submerged in flood water	26.317822	26.314773	84.875382	84.875382
13	Chakra	Sundarapur Mauje Tola Near Chilar Pathak House to Bricks Near Jalu Rai House	Keshariya	PMGSY(Gen)	On Going	No	1.279	2	Submerged in flood water	26.298965	26.298792	84.853341	84.853341
14	Chakra	NH-28 ROAD TO KHAGOPALPUR (VR20)	Keshariya	PMGSY	On Going	No	1.82	2.5	Submerged in flood water	26.368726	26.358546	84.829108	84.829108
15	Chakra	NH-28 Se Bhawanipur Road Me Md. Hussin Ke Ghar to Mai Shahan Koyari Tola	Keshariya	PMGSY(Gen)	On Going	No	1.411	2.25	Partially Submerged in flood water	26.402815	26.402815	84.754128	84.754128
16	Chakra	Repair of road from N.H.-28 to Bhirkhiya	Chakra	HR	Completed	Yes	8	1.85	Q2 Nos of Breach Reported using 1000 dia Hunt Pipe	26.511094	26.511013	85.001459	85.001459
17	Chakra	Jadu Paswan Laukaha to PWD Road near Ram Kishun Paswan	Chakra	GTSNY	Completed	Yes	0.7	2	Submerged in flood water	26.435138	26.431845	85.005535	85.005535
18	Chakra	P.M.G.S.Y. Path Chakania Bamhola Ram ke ghar se to Kanhi Tola via Brahmi Asthan	Chakra	PMGSY(SC)	Completed	Yes	2.033	7.5	Submerged in flood water	26.457006	26.50024	85.008619	85.008619
19	Chakra	NH-28 Rangardh to Prathmik Vidhyalay Kuwarpur Anawa	Chakra	PMGSY(SC)	Completed	Yes	1.507	2	Breach	26.516752	26.516752	84.949417	84.949417
20	Chakra	Dhekaha Champanan Tatandh To Manjharla	Keshariya	PMGSY(Gen)	Completed	Yes	1.655	5	A 1X10 M. Span Bridge Constructed by RLDA Fund about 20 years ago situated at own MNGSY Road Dhekaha Champanan Talahat Ch-Manjharla wash out at Ch-2500 M. due to heavy discharge flow of Tatanandh	26.322	26.322	84.8267	84.8267
21	Chakra	Bakri Parsani P.M.G.S.Y. to Bathna	Mehra	PMGSY(SC)	Completed	Yes	1.528	3	Cut/Damaged due to Heavy Rain	26.333781	26.333781	85.108856	85.108856
22	Chakra	Khokhra Chowk se to Hardev Patti	Mehra	PMGSY(SC)	Completed	Yes	3.244	2.5	Submerged in flood water	26.330716	26.331279	85.26534	85.26534
23	Chakra	LO23-Balakothi to Bakthri (VRS)	Mehra	PMGSY	Completed	Yes	3.37	2	Cut/Damaged due to Heavy Rain	26.30438	26.304291	85.266894	85.266894
24	Chakra	P.W.D Road - Sitapur	Kalyanpur	PMGSY	On Going	No	3.24	1.75	Cut/Damaged due to Heavy Rain	26.388509	26.388509	85.018317	85.018317
25	Chakra	Chakra Pura Chapara REO Path to Musahar Tola via Bakthri	Kalyanpur	PMGSY(SC)	On Going	No	1.799	3	Submerged in flood water	26.38436	26.38436	85.01426	85.01426
26	Chakra	Kalyanpur to Kesaria PWD Road via Rajpur village.	Kalyanpur	HR	On Going	No	7.1	2.5	Cut/Damaged due to Heavy Rain	26.32833	26.32833	84.896095	84.896095
27	Chakra	Husseni - Bijdhari Maffi	Keshariya	PMGSY	Completed	Yes	4.37	3	Submerged in flood water	26.31023	26.31023	84.867665	84.867665
28	Chakra	R.E.O. Road - Paduman Chapara	Keshariya	PMGSY	On Going	No	1.5	2.5	Submerged in flood water	26.31023	26.31023	84.867665	84.867665

~~Vorstand~~

new 28/1/82
AF

~~28/11/2025~~
~~Kumar~~