

Sch-XLV-Form No.154

Particulars	Details of actual measurement				Counts of area
	No.	L.	B.	D.	
Name of work -	Repair of Restoration				
of road from	P.H. 654 Path Chakansia				
Bambha Ram ke ghar to	Kannitola				
Via	Barham Astham				
Head -	F.D.R.				
Agency -	Departmental /				
	E.E. RWD (w) Div. Chackia				
Date of Measurement -					
(1) E/w excavation for	roadwork -				
	1 X	11.20 X	1.21 X	1.50 =	20.33 M ³
	2 X	7.00 X	1.27 X	1.25 =	22.23 M ³
	1 X	4.20 X	0.99 X	1.50 =	6.24 M ³
	2 X	5.60 X	1.27 X	0.95 =	13.51 M ³
	2 X	8.40 X	1.05 X	1.30 =	22.93 M ³
	3 X	8.40 X	1.10 X	1.20 =	27.72 M ³
	3 X	8.40 X	0.94 X	0.55 =	13.63 M ³
	2 X	16.80 X	0.99 X	1.65 =	54.89 M ³
	4 X	6.30 X	0.55 X	1.25 =	17.33 M ³
	1 X	18.20 X	1.27 X	1.50 =	34.67 M ³
	2 X	9.45 X	1.10 X	1.25 =	25.99 M ³
	3 X	9.10 X	1.05 X	1.35 =	38.70 M ³
	2 X	11.20 X	1.27 X	1.25 =	35.56 M ³
	1 X	16.10 X	1.21 X	1.25 =	24.35 M ³
	4 X	6.50 X	0.94 X	1.50 =	35.53 M ³
	3 X	7.70 X	0.99 X	1.10 =	25.16 M ³
	1 X	14.2 X	0.99 X	1.25 =	26.67 M ³
	1 X	11.20 X	0.99 X	1.10 =	12.20 M ³

(Continuation)

457.04 M³

Particulars	Details of actual measurement				Counts of area
	No.	L.	B.	D.	
					B.F. 1392.47H ²
	2 x 12.60	x 1.05	x 0.65		= 17.20H ²
	3 x 7.10	x 1.10	x 0.45		= 10.40H ²
	3 x 8.40	x 0.94	x 0.60		= 14.21H ²
	2 x 16.80	x 0.99	x 0.75		= 24.95H ²
	4 x 6.30	x 0.55	x 0.60		= 8.32H ²
	1 x 18.20	x 1.27	x 0.60		= 13.87H ²
	3 x 9.45	x 1.10	x 0.75		= 23.39H ²
	3 x 9.10	x 1.05	x 0.80		= 22.93H ²
					1527.74H ²
					382.42H ² B.F. = 5,84,238.20
	verified and found				
	correct				

Aswinder
 Aswinder
 25/08/2020
 SE

S. Dhillon
 21/08/20
 SE