

13

F. D. R. 2020-2021

MB No-1408

Schedule XLV-Form No. 134

સોંપાવવામાં આવેલ કાર્યોની વિગતો અને કાર્યોની પ્રગતિ

સાચી રીતે કરવામાં આવેલ કાર્યોની વિગતો

DIVISION

સાચી રીતે કરવામાં આવેલ કાર્યોની વિગતો

SUB-DIVISION

Measurement Book

સાથે આપના આદેશ
અનુસાર ૩ ઝમ ૩૦ વાગે
સાથે ૨ પોલીસ વગેરે ની
સાથે ૧૨-૧૨-૨૦ ૩૪૦ ૪૦ ૨૦ ૨૦
સાથે ૩૦ ૩૦ ૩૦ ૩૦ ૩૦ ૩૦
૩ ૦૦ ૨ ૩૦ ૩૦ ૩૦ ૩૦ ૩૦
૩

[Signature]
Executive Engineer
BWD Works Division
[Signature]

Sch. XLV-Form No. 134

_____ DIVISION

_____ SUB-DIVISION

Measurement Book

No. 1408

Name of Officer _____

Date of first entry _____

Date of last entry _____

Name of work -
 Situation of work -
 Agency by which work is executed -
 Date of measurement -
 No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work).

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

Name of work :- Restoration of road
 from Koshi Bazar to Kunalli
 via Jagmohan Tola
 (FDR Year - 2020-21)

Agency - Departmental

Authority - E.E. RWD, Works Division,
 Surpaul.

Date of measurement :- 02.09.2020

1. Laying Brick Bat in Darmac
 position.

Ch. 147 m

$$1 \times 116 \text{ m} \times 4 \text{ m} \times \left(\frac{0.5 + 0.3}{2} \right) \text{ m} = 185.600 \text{ m}^3$$

Ch. 283 m

$$1 \times 12 \text{ m} \times 4 \text{ m} \times 0.3 \text{ m} = 14.400 \text{ m}^3$$

Ch. 307 m

$$1 \times 44 \text{ m} \times 4 \text{ m} \times \left(\frac{0.5 + 0.3}{2} \right) \text{ m} = 70.400 \text{ m}^3$$

Ch. 355 m

$$1 \times 8 \text{ m} \times 4 \text{ m} \times \left(\frac{0.8 + 0.3}{2} \right) \text{ m} = 17.600 \text{ m}^3$$

Ch. 1180 m

$$1 \times 24 \text{ m} \times 4 \text{ m} \times 0.3 \text{ m} = 28.800 \text{ m}^3$$

$$1 \times 20 \text{ m} \times 4 \text{ m} \times 0.5 \text{ m} = 40.000 \text{ m}^3$$

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Ch. 1280 m					
	Nos of Bag = 400				
	Nos of bag = 300				
Ch. 1370 m					
	Nos of bag = 600				
	Nos of bag = 1300				
	Total = 2600.00				
	Total (in y. nos) = 26.00				
 02.09.2020					
J.E					

Inspection Report for Flood Damage Work

Date :

1. Name of PIUs :- E.E. RWD, Works Division Supaul.

2. Name of Block/Road :- Nirmali / Koshi Bandh to Kunauli via Jagmohan Tola.

A. For Road

1. Damage Location/Chainage : Ch. 147 m, 283 m, 307 m, 355 m, 1180 m, 1280 m, 1300 m, 1370 m.

2. Damage Length : 336 m

3. Nature of Damage : Due to flood

4. Details of Restoration Works :

- i. Material being used in Restoration work : Bamboo, EC Bag fill with local sand, Brick bats.
- ii. Equipments/Tools being used in Restoration work : JCB, Tractor, Roller
- iii. Procedure taken up in Restoration work : Felling
- iv. Restored Length : 336 m

B. For Bridge

C. For Road

5. Damage Location/Chainage : N.A.

6. Damage Length :

7. Nature of Damage :

8. Details of Restoration Works :

- i. Material being used in Restoration work :
- ii. Equipments/Tools being used in Restoration work :
- iii. Procedure taken up in Restoration work :
- iv. Restored Length :

30.11.20
A.E.

Signature of JE/AE/EE

Signature

(Name of Inspector)
30/11/20
Rural Works Department
Work Division, B.P. 408