

16

F. D. R. - 2020-2021

MBND-1411

Schedule XLV-Form No. 134

પોસ્ટલ કો જાત - PMGSY રોડ માર્ગ સંબંધિત

DIVISION

સરકારી ગ્રામીણ મંડલ કે પાલિકા બંધુક

ગ્રામીણ કમિટી

SUB-DIVISION

Measurement Book

Handwritten text in Odia script, likely a memorandum or report, covering the top half of the page.

[Signature]
Executive Engineer
BWD Weza Division
[Signature]
16/8/20

Sch. XLV-Form No. 134

_____ DIVISION

_____ SUB-DIVISION

Measurement Book

No. 1411

1.

Name of work -

Situation of work -

Agency by which work is executed -

Date of measurement -

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work).

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work :-	Restoration of road				
	from PMSY Road Mahadev mandal				
	to Abadh Narayen Mandal House				
	(FDR Year - 2020-21)				
Agency -	Departmental				
Authority -	E.E, RWD, work Division,				
	Supaul.				
Date of measurement -	02.09.2020				
1. Laying Brick Bat in					

Damage portion.

Ch. 23m.

$$1 \times 43 \text{ m} \times \left(\frac{3.8 + 3 + 2.5}{3} \right) \text{ m} \times \left(\frac{0.35 + 0.2 + 0.15}{3} \right) \text{ m} = 30.65 \text{ m}^3$$

Ch. 8.8m

$$1 \times 56 \text{ m} \times \left(\frac{5 + 3.5 + 2.8}{3} \right) \text{ m} \times \left(\frac{0.3 + 0.15 + 0.2}{3} \right) \text{ m} = 38.192 \text{ m}^3$$

Ch. 15.9m

$$1 \times 29 \text{ m} \times 3 \text{ m} \times \left(\frac{0.3 + 0.2}{2} \right) \text{ m} = 21.75 \text{ m}^3$$

Ch. 20.2m

$$1 \times 13 \text{ m} \times 3 \text{ m} \times 0.15 \text{ m} = 5.85 \text{ m}^3$$

Ch. 24.3m

$$1 \times 14 \text{ m} \times 3 \text{ m} \times \left(\frac{0.3 + 0.2}{2} \right) \text{ m} = 10.5 \text{ m}^3$$

Continuation

$$\text{Total} = 106.951 \text{ m}^3$$

Inspection Report for Flood Damage Work

Date :


1. Name of PIUs :- E.E. RWD, Works Division Supaul.
2. Name of Block/Road :- Nirmali / PMGSY Road Mahadev Mandir to Abadh Narayan Mandal House.

A. For Road


1. Damage Location/Chainage : ~~Ch. 0.00 m~~ Ch. 0.00 m, 88 m, 159 m, 202 m, 243 m.
2. Damage Length : 155 m
3. Nature of Damage : Due to flood
4. Details of Restoration Works :
 - i. Material being used in Restoration work : Brick Bats.
 - ii. Equipments/Tools being used in Restoration work : JCB, Tractor, Roller.
 - iii. Procedure taken up in Restoration work : Filling
 - iv. Restored Length : 155 m

B. For Bridge

5. Damage Location/Chainage :
6. Damage Length :
7. Nature of Damage : N.A
8. Details of Restoration Works :
 - i. Material being used in Restoration work :
 - ii. Equipments/Tools being used in Restoration work :
 - iii. Procedure taken up in Restoration work :
 - iv. Restored Length :


30.11.20
J.E.

Signature of JE/AE/EE


30/11/20
J.E.

30.11.20


30/11/20
Signature
(Name of Inspector)
Rural Works Department
Work Division, Birpur