

F. D. R - 2020 - 2021

MB No. 1399

## Schedule XLV-Form No. 134

ਮੋਗਾ/ਕਾਮਾਮ!-60-21 ਏ ਸਿਪਾਇਲਾ 44  
ਸਿ ਆਲੀ ਕਮਾਮ! DIVISION

SUB-DIVISION

**Measurement Book**

*[Faint handwritten text, likely bleed-through from the reverse side of the page]*

*[Blue ink stamp or handwritten mark]*

Sch. XLV-Form No. 134

\_\_\_\_\_ DIVISION

\_\_\_\_\_ SUB-DIVISION

# Measurement Book

No. 1299

Name of Officer \_\_\_\_\_

Date of first entry \_\_\_\_\_

Date of last entry \_\_\_\_\_

1.

Name of work -

Situation of work -

Agency by which work is executed -

Date of measurement -

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work).

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work:-	Restoration of road				
	from Lozi to Muya Tola.				
	(FDR year - 2020-21)				
Agency:-	Departmental				
Authority:-	E.E, RWD, works Division, Supaul				
Date of measurement:-	02.09.2020				
I. Laying Brick Bed in					
	Damage position.				

Ch. 70m					
	1x	13m	4m	0.3m	= 15.600m <sup>3</sup>
Ch. 692m					
	1x	41m	4m	0.3m	= 49.200m <sup>3</sup>
Ch. 730m					
	2x	17m	0.9m	0.9m	= 27.540m <sup>3</sup>
Ch. 797m					
	1x	3m	2m	1m	= 6.000m <sup>3</sup>
	Total =				98.340m <sup>3</sup>
<i>J.E</i>	02.09.2020	<i>J.E</i>	02/09/20		

Continuation

# Inspection Report for Flood Damage Work

Date :

1. Name of PUs :- E.E. RWD, Works Division Suppal
2. Name of Block/Road :- Niyamale / L.O.S. to Niyam Tale

## A. For Road

1. Damage Location/Chainage : 70m, 692m, 730m, 747m
2. Damage Length : 74m
3. Nature of Damage : Due to Flood
4. Details of Restoration Works :
  - i. Material being used in Restoration work : bridge Mats
  - ii. Equipments/Tools being used in Restoration work : 1 CG, Tractor, Rollers
  - iii. Procedure taken up in Restoration work : Filling
  - iv. Restored Length : 74m

## B. For Bridge

5. Damage Location/Chainage :
6. Damage Length :
7. Nature of Damage :
8. Details of Restoration Works :
  - i. Material being used in Restoration work : N.A
  - ii. Equipments/Tools being used in Restoration work :
  - iii. Procedure taken up in Restoration work :
  - iv. Restored Length :

30/11/20  
J.E  
Signature of JE/AE/EE

(Name of Inspector)  
Rural Works Department  
Work Division, Barwar

Signature

30/11/20