

5) F. D. R. 2020-2024

MBNO-1480


Schedule XLV-Form No. 134

ਪ੍ਰੋਜੈਕਟ ਦਾ ਨਾਂ:- ਕਮਾਨਾ ਦੇ ਕੰਮਾਂ ਦਾ
ਮ(ਕਮਾਨਾ) **DIVISION**

SUB-DIVISION

Measurement Book

પ્રમાણિત રિપોર્ટ આપવા દિ. ૧૬. ૬. ૧૯
માર્ચ ૧૯૭૩ ને જુન ૭૦ (૫-૫-૭૩)
મધ્યેથી જે પ્રમાણિત થયેલ છે તે
જો સિવજીવન સુધારા સંસ્થા આપ
આવે સત્કારે નિર્મલા જે જાન સં
નિર્મલ રિપોર્ટ આપવા દિ.


Executive Engineer
RWD Works Division

Supam

1.

Name of work -

Situation of work -

Agency by which work is executed -

Date of measurement -

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work).

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Restoration of road					For m
					Kamla patti Kunauli
					(FDR years - 2020-2021)
Agency - Departmental					
Authority - EE, RWD, works Division					
					Supaul
Date of measurement :- 01/09/2020					
1/2 Laying Brick Ball in drainage section					
Ch. 0.050 km					
1 x 54m x $\left(\frac{4.4+4+3}{3}\right)$ m x 0.3 m =					61.560 m ³
Ch. 0.141 km					
1 x 35m x 1m x 0.2 m =					0.700 m ³
Ch. 0.165 km					
2 x 3m x 1m x 0.2 m =					1.200 m ³
1 x 10m x 3.5m x 0.15m =					5.250 m ³
Ch. 0.715 km					
1 x 41m x 4m x 0.2 m =					32.800 m ³
Ch. 1.015 km					
1 x 11.3m x 2m x 0.2 m =					4.520 m ³
Ch. 1.060 km					
1 x 14.9m x 4m x 0.3 m =					17.880

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
5/7 Labour Filling empty cement bags with local sand, stitching the bags and placing including supply of sutle and 50 bag etc					
all complete Job.					
Ch. 0.050 Km, Nos of bag				2	40.00 Nos
Ch. 1.160 Km, Nos of bag				2	26.00
Ch. 3.050 Km, Nos of bag				2	72.00
Ch. 3.600 Km, Nos of bag				2	32.00
Ch. 4.000 Km, Nos of bag				2	70.00
Nos. of bag					410.00
Total (in nos) =					650.00
Total (in % nos) =					6.50

01.09.2020

J.E

01/09/20

01/09/20

Inspection Report for Flood Damage Work

Date :

1. Name of PIUs :- E.E. RWD, Works Division Supaul.
2. Name of Block/Road :- Nirmali | Kamalpur to Kunauli

A. For Road

1. Damage Location/Chainage : 141m, 165m, 715m, 1015m, 1060m, 1160m, 1310m, 1320m,
2. Damage Length : 479 m 3050m, 3600m, 4000m.
3. Nature of Damage : Due to flood
4. Datils of Restoration Works :
 - i. Manterial being used in Restoration work : Bamboo, ECB filling with local sand, Brick Bats.
 - ii. Equipments/Tools being used in Restoration work : JCB, Tractor, Roller.
 - iii. Procedure taken up in Restoration work : Filling
 - iv. Restored Length : 479 m

B. For Bridge

5. Damage Location/Chainage :
6. Damage Length :
7. Nature of Damage :
8. Datils of Restoration Works :
 - i. Manterial being used in Restoration work :
 - ii. Equipments/Tools being used in Restoration work :
 - iii. Procedure taken up in Restoration work :
 - iv. Restored Length :

N.A


30.11.20
J.E.
Signature of JE/AE/EE

Signature


30/11/20
(Name of Inspector)
Rural Works Department
Work Division, Supaul