

(10)

F. D. R. - 2020-2021

MBNO-1405

Schedule XLV-Form No. 134

પોસ્ટલ કુ. નામ :- દરયાદી ડાંગરો નિકાલ.

વેરાવળ માતા મહાલ યા કુ. **DIVISION**

મહાલ કુ.

SUB-DIVISION

Measurement Book

प्रमाणित किया जाता है कि २५
 मीटर लंबाई में कुल ५० (पचास)
 मीटर दूरी अंकित ४६२ है
 जो की विमानन प्रलय सुमा
 प्रलय अंकित २११० डिग्री
 अंक अंक प्रलय निर्माण के तहत
 से निर्माण किया जाता है


 Executive Engineer
 BWD Works Division
 Supaul
 26/8/20

Sch. XLV-Form No. 134

_____ DIVISION

_____ SUB-DIVISION

Measurement Book

No. 1405

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
		1 X 4 m	1.3 m	1.5 m	= 7.800 m ³
		1 X 3.5 m	1 m	0.3 m	= 1.050 m ³
				Total =	212.370 m ³

2. Labour for cutting 62 mm to 75 mm dia bamboo piles to size and making shoes and driving etc

Complete Job.

Ch. 2496 m

19 Nos X 1.25 m. = 23.750 m

11 Nos X 1.25 m = 13.750 m

Ch. 2516 m

9 Nos X 1.25 m = 11.250

8 Nos X 1.25 m = 10.000 m

Total = 58.750 m

3. Labour for fitting and fixing split bamboo woven Chachari in position with 20 swg G.I wire or 75 mm to 100 mm long nails alternatively including cost of G.I. wire or nails - - - - - etc

with all complete Job.

Ch. 2496 m

2 X 6 m X 2 m = 24.00 m²

1 X 6 m X 2 m = 12.00 m²

Ch. 2516 m

1 X 4 m X 2 m = 8.00 m²

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
		1 X 4m X 2 m		=	8.00m ²
				Total =	52.00m ²

4. Labour for fitting and fixing 75 mm dia bamboo runners in position at every vertical pole with 150 mm long nails or 38 Swg G.I. wire including cost of G.I. wire or nails etc---with all complete Job.

Ch. 2496 m

3 Nos X 9 m = 27.00m

3 Nos X 5 m = 15.00m

Ch. 2516 m

3 Nos X 4 m = 12.00m

3 Nos X 4 m = 12.00m

Total = 66.00 m

5. Supply of Bamboo at site.

Bamboo pilling $\times 3.0$ m + Length of Runners (m)
1.25

+ Area of Chachary m
1.413

$\left(\frac{58.750}{1.25} \times 3.0 \right) \text{ m} + 66 \text{ m} + \frac{52}{1.413}$

141 m + 66 m + 36.80 m

= 243.80

$\therefore$ Nos of Bamboo = $\frac{243.80}{6} = 40.63$

Say = 41.00

02.09.2020
J-E

Continuation

2/19

Inspection Report for Flood Damage Work

Date :

1. Name of PIUs :- E.E. RWD, Works Division Supaul.
2. Name of Block/Road :- Nirmali / Hariyahi Village to Nirmali Ghera
Barah via Mahua.

A. For Road

1. Damage Location/Chainage : Ch. 2049m, 2435m, 2496m, 2516m.
2. Damage Length : 128 m.
3. Nature of Damage : Due to Flood
4. Details of Restoration Works :
 - i. Material being used in Restoration work : Bamboo and Brick Bats
 - ii. Equipments/Tools being used in Restoration work : JCB, Tractor, Roller
 - iii. Procedure taken up in Restoration work : Filling
 - iv. Restored Length : 128 m.

B. For Bridge

5. Damage Location/Chainage :
6. Damage Length :
7. Nature of Damage :
8. Details of Restoration Works :
 - i. Material being used in Restoration work :
 - ii. Equipments/Tools being used in Restoration work :
 - iii. Procedure taken up in Restoration work :
 - iv. Restored Length :

NA

Signature of JE/AE/EE
30/11/20
30.11.20

Signature

(Name of Inspector)

Executive Engineer
Rural Works Department
Work Division, Barah