

TECHNICAL REPORT

Name of Work - FDR To Road From...Bhag Jhunki to Bhelpur.

Head - FDR

Estimated cost - 27.93.174..... Lacs

The work done estimate has been framed for the restoration (motorable) of traffic for the above road which was damage during the year 2020-2021 flash flood.

(A) Source of materials

Brick Bats - Local Kiln

Fine sand - Local

Cement Bag - Local Market

Aggregate for G.S.B - Matigara (Siliguri) by road up to site.

Bamboo - Local

Earth - Private land from 1000m lead.

(B) Rate - Carriage has been analyzed on minimum lead. Finished rate has been calculated without contractor's profit on MORD norms. Carriage of materials has been added to finished rate. Basic Rates are evaluated from rates approved by State schedule rate committee. 12% GST & 1% Labour cess has been added in the estimate in abstract part.

Sanction of estimate is much needed for payment of the work which was already done.

25/11/20 -
J.E
R.W.D
Kishanganj-1

25/11/20
A.E
R.W.D
Kishanganj-1

C
25/11/20
E.E
R.W.D
Kishanganj-1

Inspection Report for flood damage work

Date:

1. Name of PIUs- Executive Engineer RWD works division Kistangary-1

2. Name of Block/Road- Terhagachh/ Bhag Thumki to Bhalagurri,

A. For Road
1st cutting.

1. Damage Location/Chainage : 0.200 Km.

2. Damage Length : 90 m.

3. Nature of Damage : washed out, flank damage.

4. Details of Restoration :

i Material being used in Restoration

: Local sand, brick beti -

ii Equipment/Tools being used in Restoration works: Tractor.

: manual.

iii Procedure taken up in Restoration works

: 90.

iv Restored Length

B. For Bridge

1. Damage Location/Chainage : { N.A.

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration :

i Material being used in Restoration :

ii Equipment/Tools being used in Restoration works:

iii Procedure taken up in Restoration works :

iv Restored Length :

Signature
12/12/20-

Signature of JE/AE/EE

29
12/12/20 C
12/12

Signature

(Name of Inspector)

Inspection Report for flood damage work

Date:

1. Name of PIUs- Executive Engg. RWD works division, Kishangangji.

2. Name of Block/Road- Terhegachh/ Bhagthunki to Bhelaguri, 2nd cutting.

A. For Road

1. Damage Location/Chainage : 5 - 80 Km

2. Damage Length : 90 m

3. Nature of Damage : washed out flank slope

4. Details of Restoration :

i Material being used in Restoration : Brick bats -

ii Equipment/Tools being used in Restoration works: Trowel

iii Procedure taken up in Restoration works: manual

iv Restored Length : 90 m

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length : { N-A.

3. Nature of Damage :

4. Details of Restoration :

i Material being used in Restoration :

ii Equipment/Tools being used in Restoration works:

iii Procedure taken up in Restoration works :

iv Restored Length :

Scd
12/12/20 -
Signature of JE/AE/EE

12/12

C
12/12

12/12/20
Signature

(Name of Inspector)

Abstract of Cost

Name of Work:- **Bhag Jhunki to Bhelaguri**

Block :- **Terhagachh**

District:- **Kishanganj**

S.L No.	Name of cutting of roads	Chainage in Km	Length in metre	Amount (In Rs.)
1	Bhag Jhunki to Bhelaguri 1st Cutting	0.20	90.00	Rs 1924580.00
2	Bhag Jhunki to Bhelaguri 2nd Cutting	5.80	90.00	Rs 872594.00
Total Cost=				Rs 2797174.00

6921
25/12/20 -
J.E

RWD
Terhagachh


25/12/20
A.E

R.W.D
Terhagachh


25/12

E.E
R.W.D
Kishanganj - I

Technically approved for Rs. 27,97,174/-

(Rs. Twenty seven Lacs Ninety seven thousand and one hundred
Seventy four) only.


25/12/21