TECHNICAL REPORT

Name of Work - FDR To Road From Gargain to migapur.

Head - FDR

Estimated cost - 22.19.441=. Lacs

The work done estimate has been framed for the restoration (motarable) of traffic for the above road which was damage during the year 2020-2021 flash flood.

(A) Source of materials

Brick Bats - Local Kiln

Fine sand – Local

Cement Bag - Local Market

Aggregate for G.S.B - Matigara (Silliguri) by road up to site.

Bamboo - Local

Earth - Private land from 1000m lead.

(B) Rate - Carriage has been analyzed on minimum lead. Finished rate has been calculated without contractor's profit on MORD norms. Carriage of materials has been added to finished rate. Basic Rates are evaluated from rates approved by State schedule rate committee. 12% GST& 1% Labour cess has been added in the estimate in abstract part.

Sanction of estimate is much needed for payment of the work which was

already done.

341分~ J.E

R.W.D

Kishanganj-1

R.W.D

Kishanganj-1

R.W.D

Kishanganj-1

Date: Inspection Report for flood damage work
1. Name of PIUs - Executive Engineer RWD works div, Kishongery-1.
2. Name of Block/Road- Terhagachh (yargaon to sniyapur, 1st cuthing
A.For Road
1.Damage Location/Chainage: 1 Km. 2. Damage Lengh: 30 m. 3.Nature of Damage: we shedout, flank damage. 4.Details of Restoration: i Material being used in Restoration Lacal Sand, brick bets, bambooili Equipment/Tools being used in Restoration works: Tractor: iii Procedure taken up in Restoration works: iii Procedure taken up in Restoration works: sand. iv Restored Length: 30 m.
B. For Bridge 1.Damage Location/Chainage: 2. Damage Lengh 3.Nature of Damage 4.Details of Restoration i Material being used in Restoration ii Equipment/Tools being used in Restoration works: iii Procedure taken up in Restoration works iv Restored Length :
Signature of JE/AF/EE Signature

(Name of Inspector)

Signature

Inspection Report for flood damage work 1. Name of PIUs- Exe. Engineer RWD works division, Kishangary-1. 2. Name of Block/Road- Teshagachh Gargaess to soiyapur, 2nd withing. A.For Road 1. Damage Location/Chainage: 1-40 km. 2. Damage Lengh : 30m. 3. Nature of Damage : We shied out, flank damage. 4. Details of Restoration i Material being used in Restoration ii Equipment Tools being used in Restoration works: Tracefer. iii Procedure taken up in Restoration works iv Restored Length B. For Bridge B. For Bridge L.Damage Location/Chainage: Damage Lengh 3. Nature of Damage 4.Details of Restoration i Material being used in Restoration ii Equipment/Tools being used in Restoration works: iii Procedure taken up in Restoration works iv Restored Length

Signature of JE/AE/EE

ı

Signature

(Name of Inspector)

Inspection Report for Bood damage work 1. Name of PIUs - Exe. Exgineer RWD works division, Kishensony 2. Name of Block/Road- Terhagachh Gargaon to siyapur, 3rd withop. A.For Road 1. Damage Location/Chainage: 1.900 km. 2. Damage Lengh : 40 m. 3. Nature of Damage 4. Details of Restoration ii Equipment Tools being used in Restoration : Local Send, brick bet beamboring in Procedure taken up in Restoration works iii Procedure taken up in Restoration works iv Restored Length : 40 m. B. For Bridge B. For Bridge 1.Damage Location/Chainage: 2. Damage Lengh 2. Damage Lengh 3. Nature of Damage 4. Details of Restoration i Material being used in Restoration ii Equipment/Tools being used in Restoration works: iii Procedure taken up in Restoration works iv Restored Length

Signature of JEVAF/EE 92/12/10 [2/12

(Name of Inspector)

Scanned by CamScanner

Abstract of Cost

of Work:-

Gargaon to Miya Tola

ck :-

S.L No.

1 2

3

Terhagachh

fistrict:-

riet:- Kishanganj				
	Name of cutting of roads	Chainage in Km	Length in metre	Amount (In Rs.)
	Gargaon to Miya Tola 1st Cutting	1.00	30.00	Rs 472205.00
C	Gargaon to Miya Tola 2nd Cutting	1.40	30.00	Rs 745382.00
G	Gargaon to Miya Tola 3rd Cutting	1.90	40.00	Rs 1061854.00

RWD

Terhagachh

R.W.D Terhagachh

Rs 2279441.00

R.W.D Kishanganj - I

Total Cost=

Technically approved for \$ 22,79,441=50.

(RS Twenty Lacs seventy thousand and tour rundred

Foots one Jonly.

Scanned with CamScanner