

TECHNICAL REPORT

Name of Work – FDR To Road From.....

Head – FDR

Estimated cost – 25.5556 Lacs

The work done estimate has been framed for the restoration (motarable) of traffic for the above road which was damage during the year 2020-2021 flash flood.

(A) Source of materials

Brick Bats – Local Kiln

Fine sand – Local

Cement Bag – Local Market


Aggregate for G.S.B – Matigara (Silliguri) by road up to site.


Bamboo – Local


Earth – Private land from 1000m lead.

(B) Rate - Carriage has been analyzed on minimum lead. Finished rate has been calculated without contractor's profit on MORD norms. Carriage of materials has been added to finished rate. Basic Rates are evaluated from rates approved by State schedule rate committee. 12% GST & 1% Labour cess has been added in the estimate in abstract part.

Sanction of estimate is much needed for payment of the work which was already done.


J.E.
R.W.D
Kishanganj-1


A.E.
R.W.D
Kishanganj-1


E.E.
R.W.D
Kishanganj-1

Inspection Report for Flood damage work

Date:

1. Name of P.U.s- Executive Eng. RWD works division, Kishanganj-1.

2. Name of Block/Road- Terhagachh/ 1040 dhaveli herijan to/a road
to the Kur Anisapur road dhaveli, 2nd cutting

A. For Road

1. Damage Location/Chainage : 0.00 km.

2. Damage Length : 42 m.

3. Nature of Damage : washed out, flank damage.

4. Details of Restoration :

i Material being used in Restoration

: Local sand, brick bats, Bamboo.

ii Equipment/Tools being used in Restoration works: Tractor.

iii Procedure taken up in Restoration works : manual.

iv Restored Length : 42 m.

B. For Bridge

1. Damage Location/Chainage : { N.A.

2. Damage Length : {

3. Nature of Damage : {

4. Details of Restoration : {

i Material being used in Restoration :

ii Equipment/Tools being used in Restoration works:

iii Procedure taken up in Restoration works :

iv Restored Length :

Signature of JE/AE/EE

Signature

(Name of Inspector)

Inspection Report for flood damage work

Date:

1. Name of PIUs- Executive Eng. RWD works division Kishanganp-1
2. Name of Block/Road- Teshagachh/ L040 dhevelli herijam tola road to
Hokur Amirpur road dhevelli, 2nd cutting

A. For Road

1. Damage Location/Chainage : 0.20 km.
2. Damage Length : 50m.
3. Nature of Damage : washed out, flank damage.
4. Details of Restoration :
i Material being used in Restoration : Local sand, brick bats, etc.
ii Equipment/Tools being used in Restoration works: Tractor.
iii Procedure taken up in Restoration works : manual.
iv Restored Length : 50m.

B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration :
i Material being used in Restoration :
ii Equipment/Tools being used in Restoration works:
iii Procedure taken up in Restoration works :
iv Restored Length :

Signature of JE/AF/EE

Signature

(Name of Inspector)

Inspection Report for flood damage work

Date:

1. Name of PIUs- Executive Eng. RWD works division, Kishoreganj-1.

2. Name of Block/Road- Terhagachh/ Lo 40 dhaveli hazijsan tola road
to thekur Amirpur road dhaveli 3rd cutting

A. For Road

1. Damage Location/Chainage : 0.800 km.

2. Damage Length : 60m.

3. Nature of Damage : washed out flank damage.

4. Details of Restoration :

i Material being used in Restoration

: Brick bats, Local sand, sand bags.

ii Equipment/Tools being used in Restoration works:

: Tractor.

iii Procedure taken up in Restoration works

: manual.

iv Restored Length

: 60m.

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration :

i Material being used in Restoration

:

ii Equipment/Tools being used in Restoration works:

:

iii Procedure taken up in Restoration works

:

iv Restored Length

:

Signature of JE/AE/EE

12/12/20

12/12/20

12/12

Signature

(Name of Inspector)

Inspection Report for flood damage work

Date:

1. Name of PIUs- Executive Eng. RWD works division, Kishanganpur.

2. Name of Block/Road- Texhagachh/ L040 daveli harijam to road
to thekur Anantpur road daveli, 4th
cutting.

A. For Road

1. Damage Location/Chainage : 1.20 km.

2. Damage Length : 50m.

3. Nature of Damage : washed out Flank damage.

4. Details of Restoration :

i Material being used in Restoration : Brick bats, local sand, steel,
bags.

ii Equipment/Tools being used in Restoration works: Tractor.

iii Procedure taken up in Restoration works : manual.

iv Restored Length : 50m.

B. For Bridge

1. Damage Location/Chainage : { N-A.

2. Damage Length : {

3. Nature of Damage : {

4. Details of Restoration :

i Material being used in Restoration :

ii Equipment/Tools being used in Restoration works:

iii Procedure taken up in Restoration works :

iv Restored Length :

Signature of JE/AE/EE

Senj

12/12/20

12/12/20

12/12

Signature

(Name of Inspector)

Inspection Report for flood damage work

Date:

1. Name of PIUs- Executive Eng. RWD works division, Kishanganj-1.

2. Name of Block/Road- Terhagechh / Lo 40 dhaveeli harizon tola road to thekur Anairpur road dhaveeli, 5th circle

A. For Road

1. Damage Location/Chainage : 1.40 km.

2. Damage Length : 150 m.

3. Nature of Damage : washed out flank damage.

4. Details of Restoration :

i Material being used in Restoration

: Brick bats, local sand, sand bag, bamboo.

ii Equipment/Tools being used in Restoration works:

: Tractor,

iii Procedure taken up in Restoration works

: manual,

iv Restored Length

: 150 m.

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration :

} N-A.

i Material being used in Restoration

:

ii Equipment/Tools being used in Restoration works:

:

iii Procedure taken up in Restoration works

:

iv Restored Length

:

Signature of JE/AE/EE

Seal
12/12/20

12/12/20

12/12

Signature

(Name of Inspector)

Abstract of Cost


Name of Work:- L040 dheveli Harijan Tola Road to Thekur Amirpur Road Dheveli


Block :- Terhagachh

District:- Kishanganj

S.L No.	Name of cutting of roads	Chainage in Km	Length in metre	Amount (In Rs.)
1	L040 dheveli Harijan Tola Road to Thekur Amirpur Road Dheveli 1st cutting	0.00	42.00	Rs 538023.00
2	L040 dheveli Harijan Tola Road to Thekur Amirpur Road Dheveli 2nd cutting	0.20	50.00	Rs 411917.00
3	L040 dheveli Harijan Tola Road to Thekur Amirpur Road Dheveli 3rd cutting	0.80	60.00	Rs 397977.00
4	L040 dheveli Harijan Tola Road to Thekur Amirpur Road Dheveli 4th cutting	1.20	50.00	Rs 355755.00
5	L040 dheveli Harijan Tola Road to Thekur Amirpur Road Dheveli 5th cutting	1.40	150.00	Rs 851894.00
Total Cost=				Rs 2555566.00

Scrp
25/12/20 -
J.E
RWD
Terhagachh


A.E
25/12/20
R.W.D
Terhagachh


E.E
25/12
R.W.D
Kishanganj - I

Technically approved for ₹ :- 25,55,566 = 00

(Rs. Twenty five lacs fifty five thousand and five hundred

Sixty six) only .


25/1/21