

GENERAL ABSTRACT

Name of Road Sukki High School to Saraiya Ghat Tak

District Vaishali

Block Patepur

Division Mahuwa

Length of Road (in Km)

1.670 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	3.140
2	Sand Filling	0.061
3	Earthwork	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	3.202
TOTAL COST OF PROJECT IN LACS =		3.202

3.20 lacs

Ref
10.12.20
JE
RWD

Ref
19/12/20
AE
RWD

Ref
15.12.20
EE
RWD

Technically approved for Rs 3.20 lacs (Rs. 3200000) only,
Shoukatee (worky & material) only.

Ref
23.1.21
Superintending Engineer
R.W.D. WORKS CIRCLE
MUZAFFARPUR

Ref

SI. No.	SDB SL NO	MORD Ref. No	Description	Unit	QUANTITY	RATE	AMOUNT (in Rs.)
1		13.7 SoR Bihar Govt. (1985)	Jhama metal Labour for consolidation in Jhama metal by Road Roller in proper grade camber and super elevation dry and wet rolling including cost of running charge of roller diver and khalasi making and maintaining diversion light barrier - do - do- danger signal etc. all complete .				
			Appendix - I	Cum	154.44		
			Total		154.44	2033.34	314029.03
2		11.20	Sand Filling Filling in foundation trenches as per drawing and technical specification Clause 305.3.9				
			Appendix - II	Cum	13.500		
			Total		13.50	454.53	6136.16
			SUB TOTAL =				326301.35

B 320165:19
Bny Rs 320165=0

57.
15.12.20
E.E.

15.12.20
A.E.

15.12.20
A.E.

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - *E.E. PWD, Mohua-*
2. Name of Block/Road - *patipura, Sukrai high school to Baruiya ghat talu.*

A. For Road

1. Damage Location/Chainage : *100.0000, 110.0000, 113.0000.*
2. Damage Length : *22.5000*
3. Nature of Damage : *Flood.*
4. Details of Restoration Works
 - i. Material being used in Restoration works : *Brick balls, sand.*
 - ii. Equipments/Tools being used in Restoration works :
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :

B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration works :
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :

Rohit
10.12.20
Signature of JE/AE/EE

Asad
10/12/20
A.E.

15.12.20

Geny
15.12.20
Signature

(Name of Inspector)