TECHNICAL REPORT

Name of Work - FDR To Road From PHGSY TO Malka man

Head

- FDR

Estimated cost

-... 12:5861.... Lacs

The work done estimate has been framed for the restoration (motarable) of traffic for the above road which was damage during the year 2020-2021 flash flood.

(A) Source of materials

Brick Bats - Local Kiln

Fine sand – Local

Cement Bag - Local Market

Aggregate for G.S.B - Matigara (Silliguri) by road up to site.

Bamboo - Local

Earth – Private land from 1000m lead.

(B) <u>Rate</u> - Carriage has been analyzed on minimum lead. Finished rate has been calculated without contractor's profit on MORD norms. Carriage of materials has been added to finished rate. Basic Rates are evaluated from rates approved by State schedule rate committee. 12% GST& 1% Labour cess has been added in the estimate in abstract part.

Sanction of estimate is much needed for payment of the work which was

already done.

R.W.D

Kishanganj-1

R.W.D

Kishanganj-1

E.E

R.W.D

Kishanganj-1

Date: Inspection Report for	flood damage work
1. Name of PIUs- Executive Eng	winces Kishangany - 1
2. Name of Block/Road- Kishangen	vinces Kishangany-I nj / pMorsy to Malhema
A.For Road	
1.Damage Location/Chainage: 25m. 2. Damage Lengh 3.Nature of Damage : filtrool 4.Details of Restoration : i Material being used in Restoration ii Equipment/Tools being used in Restoration wo iv Restored Length	: Bamboo, Sand B-but e
B. For Bridge	
1.Damage Location/Chainage:	
2. Damage Lengh	
3. Nature of Damage 4. Details of Restoration	
i Material being used in Restoration	
ii Equipment/Tools being used in Restor	:
iii Procedure taken up in Restoration wor	ke •
iv Restored Length	:
Signature of JE/AE/EE	Cialia Milatar
Composition of the Alberta Composition of the Al	Signature

(Name of Inspector)

Detailed Estimate

PMGSY to Malhana

Rato Unit **Qnty** Name of work Width Height No Longth Item Providing and laying reinforced cement concrete SI No 47819.00 4781.89 pipe NP3 for culverts on first class bedding of rm 10.00 granular material in single row including fixing 2.50 4 collar with cement mortar 1:2 but excluding excavation, protection works, backfilling, 336,00 Providing and cutting of 62 mm to 75 mm dia 120 2,80 215.00 27660.00 bamboo piles to size and making shoes, all 100 50.20 2.15 rm 551.00 Total complete job ----E/I 120.00 Providing, fitting and fixing 62 mm to 75 mm dia 20.00 40.00 4565.00 bamboo runners in position at every vertical pile 28.53 10.00 4 rm 160.00 Total with 150 mm long nails or 38 swg G.I. wire 46.37 2.10 Providing and filling empty cement bags with 19.20 1.15 1 22.38 local sand, stitching the bags and placing 2.70 9.75 0.85 21.60 including supply of sutil etc. all complete job -1.50 1.20 12.00 cum 90.35 101414.00 Total 38.14 Nos 2659.00 E/I 3190.71 cft Say 249.38 2.10 25.00 4.75 Providing laying and spreading brick bats in Road ditches all complete as per approved 1 134.81 2.85 4.30 11.00 1 50.22 1.35 931818.00 design, specifications and direction of E/I 3.10

12.00

TOTAL Rs 133593.00 Add 12 % GST Rs 11133.00 Add 1 % L. Ces Rs 11133.00

Total Cost Rs 1258002.00

Say. RS. 1258000/-

2145.02

cum

434.41

Total

Kishanganj-1

R.W.D Kishanganj-1 Kishanganj - I

1113276.00

Amount

Technically approved for 1. 1258000/-

.....)only