

TECHNICAL REPORT

Name of Work - FDR To Road From *Baibo Porey Road to Kolskitha Road*
Head - FDR
Estimated cost - *2,24,374* Lac

The work done estimate has been framed for the restoration (motorable) of traffic for the above road which was damage during the year 2020-2021 flash flood.

(A) Source of materials

Brick Bats - Local Kiln
Fine sand - Local
Cement Bag - Local Market
Aggregate for G.S.B - Matigara (Silliguri) by road up to site.
Bamboo - Local
Earth - Private land from 1000m lead.

(B) Rate - Carriage has been analyzed on minimum lead. Finished rate has been calculated without contractor's profit on MORD norms. Carriage of materials has been added to finished rate. Basic Rates are evaluated from rates approved by State schedule rate committee. 12% GST & 1% Labour cess has been added in the estimate in abstract part.

Sanction of estimate is much needed for payment of the work which was already done.

J.E.
10/12/20
J.E
R.W.D
Kishanganj-1

R.W.D.
11/12/2020
A.E
R.W.D
Kishanganj-1

E.E.
12/12/20
E.E
R.W.D
Kishanganj-1

Inspection Report for Flood damage work

Date: 13.12.20

1. Name of PIUs- R.W.D (W) Div. Kishanpur-1

2. Name of Block/Road- Bahadurganj, Baiza PMGSY road to Kolbhitha Road

A. For Road

1. Damage Location/Chainage : ch - 0.300 K.M

2. Damage Length : 25.00 M

3. Nature of Damage : washed out near old culvert.

4. Details of Restoration :

i Material being used in Restoration

: Soil, Brick bats

ii Equipment/Tools being used in Restoration works: JCV, Tractor etc, roller etc.

iii Procedure taken up in Restoration works

: Manual

iv Restored Length

: 25.00 M

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration :

i Material being used in Restoration

:

ii Equipment/Tools being used in Restoration works:

:


iii Procedure taken up in Restoration works


:


iv Restored Length

:

N.A



Signature of JE/AE/EE


13/12/2020
BB


13/12/20


Signature

(Name of Inspector)


13.12.20
3.E


Detailed Estimate


ne of work :-

Baisa PMGSY Road to Kolbhitha Road

| Sl No | Item | No | Length | Width | Height | Qty | Unit | Rate | Amount |
|-------|--|----|--------|-------|--------|--------|--------|------|-------------|
| 1 | Construction of embankment with approved materials deposited at site from roadway cutting and, all complete job -----E/I. | 1 | 25.00 | 5.90 | 2.50 | 368.75 | | | |
| | | | | | | Total | 368.75 | cum | 189.45 |
| 4 | Providing laying and spreading brick bats in Road ditches all complete as per approved design, specifications and direction of E/I | 1 | 25.00 | 4.00 | 0.60 | 60.00 | | | |
| | | | | | | Total | 60.00 | cum | 2145.02 |
| | | | | | | | | | 128701.00 |
| | | | | | | | | | TOTAL |
| | | | | | | | | | 198561.00 |
| | | | | | | | | | Add GST@12% |
| | | | | | | | | | 23827.00 |
| | | | | | | | | | Add L.C@1% |
| | | | | | | | | | 1986.00 |
| | | | | | | | | | TOTAL - |
| | | | | | | | | | 224374.00 |

Say RS - 224400/-



10/12/20
J.E
RWD
Bahadurganj-1


11/12/2020
A.E
R.W.D
Bahadurganj


12/12/20
E.E
R.W.D
Kishanganj - I

Technically approved for Rs. 224400/-

(Rs. Two Lacs ^{four} ~~twenty~~ thousand and Four hundred.) only


25/1/24