

RURAL WORKS DEPARTMENT



GOVERNMENT OF BIHAR

CIRCLE – R.W.D. works Circle, Kishanganj

DIVISION – R.W.D. works Division , Kishanganj-2

Name of Work - Khairibari Bengal Boarder to Kapranga

Block - POTHIA

Estimated cost - Rs 616803.00

Year : 2020-21

TECHNICAL REPORT

Name of Work – FDR To Road From... *Khutbani Begul Border to Kabra*

Head – FDR

Estimated cost – *6.22000/-* Lacs

The work done estimate has been framed for the restoration (motorable) of traffic for the above road which was damage during the year 2020-2021 flash flood.

(A) Source of materials

Brick Bats – Local Kiln

Fine sand – Local

Cement Bag – Local Market

Aggregate for G.S.B – Matigara (Silliguri) by road up to site.

Bamboo – Local

Earth – Private land from 1000m lead.

- (B) **Rate** - Carriage has been analyzed on minimum lead. Finished rate has been calculated without contractor's profit on MORD norms. Carriage of materials has been added to finished rate. Basic Rates are evaluated from rates approved by State schedule rate committee. 12% GST & 1% Labour cess has been added in the estimate in abstract part.

Sanction of estimate is much needed for payment of the work which was already done.

[Signature]
J.E
R.W.D
Kishanganj-2

[Signature]
A.E
R.W.D
Kishanganj-2

[Signature]
E.E
R.W.D
Kishanganj-2

Inspection Report for flood damage work

Date:

1.Name of PIUs-

E-E-R.W.D (W) DIV- Kishangan-2

2.Name of Block/Road-

Poltina/Khairibani Bengal Border to
Kabranga

A.For Road

1.Damage Location/Chainage : ch- 1.50km 2.20km

2. Damage Lengh : 53.00m

3.Nature of Damage : washed and Heave Damage

4.Details of Restoration :

i Material being used in Restoration

: Local Sand Bales Bates
Bamboo.

ii Equipment/Tools being used in Restoration works:

iii Procedure taken up in Restoration works

: Tractor, Mammul

iv Restored Length

: 53.00m

B. For Bridge

1.Damage Location/Chainage :

2. Damage Lengh :

3.Nature of Damage :

4.Details of Restoration :


i Material being used in Restoration

ii Equipment/Tools being used in Restoration works:

iii Procedure taken up in Restoration works

iv Restored Length

Signature of JE/AE/EE


12/11/14
AB


Signature

(Name of Inspector)

Detailed Estimate **Khairibari Bengal Boarder to Kapranga**

No	Item	No	Length	Width	Height	Qty	Unit	Rate	Amount
1	Providing laying and spreading brick bats in Road ditches all complete as per approved design, specifications and direction of E/I	1	22.00	4.25	0.35	32.73			
		1	30.00	5.15	1.10	169.95			
						202.68	cum	2145.02	434742.00
2	Providing and filling empty cement bags with local sand, stitching the bags and placing including supply of sutli etc. all complete job ---E/I	1	22.00	1.20	1.50	39.60			
		1	30.00	1.10	1.80	59.40			
		Total				99.00	cum		
		=	3496.19 cft		Say	2913.00	Nos	38.14	111102.00
TOTAL									545844.00
							Add 12 % GST o	Rs 65501.00	
							Add 1 % L. Cess	Rs 5458.00	
							Total Cost	Rs 616803.00	

Add Sanjivani fee (+) M 5200 200
M 6,22003 200
Says M 6,22 000 200

Kun
12/12/2020
J.E
RWD
POTHIA

Yee
12/1/2021
A.E
R.W.D
POTHIA

S.E
R.W.D
Kishanganj
12/1/21

Technically approved for ₹ 6,22 000 /-

(Rs. Six.....Lacs.....Twenty two thousand and.....

.....)only

AK
30/1/20
अधीक्षण अभियन्ता
ग्रामीण कार्य विभाग
कार्य अंचल, किशंगंज