PDF Compressor Free Version



Inspection Report For Flood Damage Work

100				
100)a	4	_	
. **	/ Cl		G.	

1 Name of PIUs:

Gopalgani - 2

2 Name of Block/Road: Bai/Courthpus / Hamidpus Bargeg REO Road Se Dus For Road Tou Hote Luc Augustosi

1 Damage Location / Chainage: 0.00 m ≠0

2 Damage Length:

Heavy Rain / Flood. 3 Nature of Damage:

4 Details of Restroration Works:

i. Material being used in Restoration Works: Brick Gats

ii Equipments / Tools being used in Restoration Works: TCB, Pontos, Trou, Beldg, Shawed.

iii Procedure taken up in Restoration Works:

iv Restored Length:

178.000

B For Bridge

N/A.

- 1 Damage Location / Chainage:
- 2 Damage Length:
- 3 Nature of Damage:
- 4 Details of Restroration Works:
 - i. Material being used in Restoration Works:
 - ii Equipments / Tools being used in Restoration Works :
 - iii Procedure taken up in Restoration Works:

iv Restored Length:

(NEXe & Little Electroneer R.W.D. W.D.

Hathua



ग्राम्कां कार्त विभाग

Rural Works Department, Govt. of Bihar

FLOOD DAMAGED REPAIR (F.D.R.)

STATE :- BIHAR

DISTRICT :- GOPALGANJ

BLOCK :- BAIKUNTHPUR

Hamidpur Bangra REO Road Se Dusad Toli Hote Hue Aaganbari Kendra

ESTIMATED COST - RS.

1328500.00

SUBMITTED BY :-EXECUTIVE ENGINEER RWD (W) DIVISION GOPALGANJ-2

Report

Name of Work

:- Motorable work of Hamidpur Bangra REO Road Se Dusad Toli Hote Hue Aaganbari Kendra

Estimated Cost

:- 1328500.00

Total length of Road

Description :- The present estimate has been farmed under the supervision of Assistant engineer in accordance with the order of Executive Engineer, RWD, WD Gopalganj-2, letter No. - 1574 dated 18-08-2020. The part of above mentioned road has been damaged due to heavy rain/flood. And due to this damage the transporation has been obstructed. The immediate motorable work is necessary in public interest. Villagers will be benefitted by the completion of this motorable work.

km

In the estimate there has been a provision of repairing the damaged part of the road & making it motorable by filling brickbats. In the context of post flood scenario there is still the flow of water which prevails through the damaged part of the road.

In this estimate the rate of raw materials and labour wages has been prepared after the analysis of new rate. This estimate is as per the specifications. The estimate is devoted to technical and administrative acceptance.

(M) 2020 J.E.

4.E.

25/10/10 E.E.

Detailed Estimate For Motorable Work in Road from Hamidpur Bangra REO Road Se Dusad Toli Hote Hue Aaganbari Kendra damaged due to Heavy rain/flood for year 2020-2021

Items	No.	L (M.)	W (M.)	D (M.)	Qty.	Unit	Rate	Amount
Providing brick bats billed in ditches including all cost of labour & material with all	341	13****** *********						
CH - 0 M to M	1 1	12.00	3.00	0.80	28.80	МЗ		
	1	11.00	0.60	1.20	7.92	МЗ		
	1	5.00	0.65	1.10	3.58	МЗ		
	1	20.00	0.50	0.95	9.50	МЗ		
	1	24.00	1.00	1.00	24.00	МЗ		
	1	20.00	1.40	1.50	42.00	МЗ		
	1	30.00	2.60	1.50	117.00	МЗ		
	1	15.00	2.20	1.40	46.20	M3		
	1	16.00	2.60	1.00	41.60	M3		
	1	25.00	2.10	1.30	68.25	M3		
	1	8.00	3.00	1.50	36.00	M3		
Less for H.P.	0	1.23	1.23	5.00	0.00	М3	23/12:11	18070022
					541.85	М3	2427.65	1315410.01
Providing & laying 1000 MM Dia NP3 Hume Pipe in single row -do-do- complete job.	0	2,50			0.00	м	2744 · 5 a 4159.56	0.00 /30 7 ms L
2000 1 COL								1315410.01
Add 1 % Contigency								13154.10
201000001 = 2715							Total	1328564.11
							Say	1328500.00

Ri 1320072~ Sey Ri 13.200 Cen

9511012020 J.E. Jan 10.70 20

A.E.

E.E. 10/20

Technically Approved for Rs 13.200 law (Pupes Thefun law Twenty Thousand) only

21/01/2

Superintending Engineer RWD Works Circle, Siwan Reuns | 127 | 21 | ot | U